RECORDED LAKE COUNTY, MI.

LAKE COUNTY REMONUMENTATION (BER 0 0 3 PAGE 0 2 0 8

FEB 1 8 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Dec 13 3 42 PM '93

Fo	r corners in	Located In:	Corner Code ##	REGISTER OF DEEDS
	(County)	Eocated III.	Comer Code 34	REGISTER OF DEEDS
1.	Public Land Survey	T	G-13	
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R	Re	gister of Deeds Stamp & File Number
	1 at No.	Paperdad Diet		
		recorded Plat		- ABCDEFGHIJKL
				3
I	Robert L. Wetherell	, in a field survey on	October 28, 93	5
in Cur Ma abo Co ext	hereby certify that under req ines 1 and 2 above were in trent manual of survey instru- nagement or by a decree of a ove were in conformance with urt of Law; established, ro pressed below:	quirements of P.A. 74, Michigan P.A. nonformance with regulations an uctions of the United States Depart a Court of Law and/or that the corne the rules of the Michigan Board or e-established, monumented, re-roorners, all in the same town ar	of 1970, the corner points mentioned of rules therefore as required in the tment of the Interior, Bureau of Lander points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a monumented, recovered, found as	6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
	mana talah atradalah		d/or out a revent materation.	13
Α.	6-13 - (Section corner	monument and accessories and common to Sections 33 & 34, T	[17N, R13W, on County Line)	1956 - George Blass, LS 5489
	#1 24" B. Oak N #2 10" W. Pine 1907 - George W Identified Orig #3 10" W. Pine	142 ⁰ W 32 Links N49 ⁰ E 20 Links Vest, Surveyor Jinal Corner	1938 Bruce Elliott, USFS (Jr. Fore: Found wooden stake for monument #5 Cedar Post S16°E 6 Links (3.96')	Surveyor West's Witnesses.
8.	Description of corner e	vidence found and/or method a	applied in restoring or reestablishing	·
	G-13 - <u>(Section corner</u>	common to Sections 33 & 34, T	17N, R13W, on County Line)	
	location. Cond	lition of accessories are: #1	n pipe with pices of broken glass a Gone, #2 Found Stump, #3 Found Stum Free down, #9 Found in good condition	mp, #4 Gone, #5 Found in good
C.	Description of monume	ent for corner and accessories	established to perpetuate locating t	he position of the corner:
	G-13 - (Section corner	common to Sections 33 & 34, T	117N, R13W, on County Line)	
	•	ass 1/2" Iron with 3/4" x 24" R cuation of the position of the	Re-rod with Lake County Brass Cap a original corner.	nd is accepted as a careful and

18" Red Maple S18°W 32.30' (60d nail in SE side of tree)

10" S. Maple N86°W 32.92' (60d nail in South side of tree)

12" S. Maple S71°E 20.90 (60d nail in NE side of tree)

8" S. Maple N22°E 16.73' (60d nail in NN side of tree)

Signed by Surveyor's Michigan License No.

Z-13-93

24624

FORM APPROVED BY MICHIGAN STATE BOARD OF JAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ROBERT L

WETHERELL

LAND **SURVEYOR**

NO.

Approved by Peer Review Group December 6, 1993 Robert L. Wetherell, County Representative 22 2 W