LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N., R. 11 W.	G-4; I-7; I-8
2. PROPERTY CONTROLLING IN SECTION 22	,T. 18 N., R. 11 W.	3
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on July 9, 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__ , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

Cor 3
Set 1" x 36" pipe & Ced. Gd.
Post w/loc. tag
21" W. Oak S30°E 30.1'
7" Maple (in clump of six) S70°W 16.1'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-4 Restored corner on split of ~~corner~~ ROW. Cor. fn. post 29' E & W (line fns. E & W), which fits 1/8 line fn. E 1/4 mile to N.

I-7 Found 3/4" x 4' pipe and old connecting rod which fit Geo. Johnson Wit. of Record. Corner is on southerly edge of E-W Sand Trail Road.

I-8 Found 3/16" x 1" x 2' iron which fits two Geo. Johnson Wit. of Record. Survey and fence built in 1918.

Cor 3 Established corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-4	I-7	I-8
Set DNR Mon. (bur.6")	Fd. pipe added DNR	Fd. Iron added DNR Mon.
7" Maple S33°E 69.4'	Mon. (buried)	& Ced. Gd. Post
16" Ironwood S58°W 19.4'	22" R. Oak N 8°E 30.2'	22" R. Oak N40°E 21.3'
Set Ced. post w/loc.	28" R. Oak S35°E 46.7'	15" Twin Map. S73°W 17.8'
tag Due E 33'	6" R. Oak S55°W 23.7'	N-S Fence Due E 0.5'
N-S Trail Rd. Due E 18'±	Set loc. tag on corn. fen.	
	post S 5°W 18.5'	
	(fn. W & S; also Fn. E at33')	

SIGNED BY Carl F. Roser DATE 9-24-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN (SEAL) CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM735
DOUBLEDAY BROS. & CO. KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS