# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF–: | LOCATED IN–: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. 18 N., R. 12 W. | G-3; H-3; I-3; I-4 |
| 2. PROPERTY CONTROLLING IN SECTION | , T. N. S., R. E. W. | |
| 3. MISCELLANEOUS PROPERTY IN SECTION | , T. N. S., R. E. W. | |

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 5, 19 75, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~

C. (continued)

I-4

Found concrete mon. & set cedar post

| | | |
|---|---|---|
| 6" Maple | S20°W | 55.35 |
| 6" W. Oak | N76°E | 50.73 |
| 6" Maple | N45°W | 27.70 |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-3 Recovered old cedar stake bottom in E-W skidding trail from three F. Jones witnesses, dated 1936. Jones found stake & one U.S.B.T. (tamarack with marks - plain).

H-3 Found stone from one Geo. Johnson witness, dated June 1922.

I-3 Found iron from two F. Jones witnesses which fits remains of one U.S.B.T.

I-4 Found concrete monument by R.L.S. Clint Cole. Corner is 70' west of N-S trail road and on southeast corner of wildlife cutting.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3

Found wood stake, added DNR mon.

| | | |
|---|---|---|
| 9" Cedar | N35°W | 17.8 |
| 7" Cedar | S15°E | 8.0 |
| 8" Cedar | S30°W | 27.3 |
| Set cedar post w/loc. tag | | |
| | Due S | 16.5 |

H-3

Found stone & added DNR mon. and cedar post

| | | |
|---|---|---|
| 6" B. Oak | N30°E | 56.4 |
| 6" W. Oak | N60°E | 51.4 |
| Power Pole | S85°E | 109.70 |

I-3

Found iron & added DNR mon. and cedar post

| | | |
|---|---|---|
| 13" B. Oak | N45°W | 58.8 |
| 9" R. Oak | N25°E | 12.3 |
| 12" B. Oak | S28°W | 38.0 |

SIGNED BY Carl F. Roser 9-4-75 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

CARL F. ROSER (SEAL) LAND SURVEYOR No 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET