# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF—: | LOCATED IN—: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. 18 N., R. 12 W. | C-10; D-9 |
| 2. PROPERTY CONTROLLING IN SECTION 29 | T. 18 N., R. 12 W. | 5 |
| 3. MISCELLANEOUS PROPERTY IN SECTION 29 | T. 18 N., R. 12 W. | *653.7' W. of #9 (Sec. 29) &653.4' E of D-10 |
| 4. LOT NO. _____ , RECORDED PLAT _____ | | |
| 5. PRIVATE CLAIMS _____ | | REGISTER OF DEEDS STAMP AND FILING NUMBER |

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 7, 19 77, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on June 13, 19 77, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and subsequent~~

C. (continued)

```
                    *
Fd. 1" "T" iron
12" B.Oak    N68°E    36.6
 5" B.Oak    S30°E    39.0
Set Ced.Post beside fd. iron
             Due N    33'
```

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-10 Fd. & accepted 1/4 Cor. as restored at single proportion position by RLS, Matt McClung. McClung notes that corner & Wits. by Blass were gone.

D-9 Restored 1/4 Cor. per G.Blass certificate survey in NE 1/4 of Sec. 29, dated Oct. 1970. Restored at double distance & on line across ctr. & N 1/8 on N-S 1/4 line of Sec. 29. Fd. one Blass wit.

5 Fd. "T" Ir., Cert. Sur. by Blass, for NW corner of W 1/2-SW 1/4-NE 1/4 of Sec. 29' dated Oct., 1970.

* Fd. "T" Ir. for SW Corner of E 1/2-SW 1/4-NE 1/4 of Sec. 29.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

```
C-10                          D-9                          5
Fd. 3/4" iron rod; raised     Set 5/8"X40" rod in ctr.N-S rd.  Fd. "T" iron w/RLS cap, added
w/1/2"X7" pipe                & in line w/old fn's. to E & W   Ced.Post w/loc. tag
Tel. Box     N40°E    48.0    14" W.Oak    N45°W    34.5       5" B.Oak     Due E    11.4
 3" W.Pine S34°E    50.2      6" B.Oak    S34°E    54.2       4" B.Oak     S20°E    10.7
12" B.Oak    S55°W    31.1   20" B.Oak    S50°W    53.2       ℄ N-S rd.    Due W    15'
Set Ced.Post w/loc. tag       Set Ced.Post w/loc. tag
             Due S    33'                  Due W    33'
```

SIGNED BY Carl F. Roser 5-15-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN — CARL F. ROSER — LAND SURVEYOR — (SEAL) No. 12028 — REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET