LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N., R. 12 W.	G-9; I-8
2. PROPERTY CONTROLLING IN SECTION 21	T. 18 N., R. 12 W.	1; 2
3. MISCELLANEOUS PROPERTY IN SECTION 21	T. 18 N., R. 12 W.	*653.0'-N, of #10 (Sec. 21) & 653.0'S of E-8.
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 22, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on July 5, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and in subsequent restoration

2			*		
Set 5/8"X40" rod w/ RLS Cap & Ced. Post w/loc. tag			Set 5/8"X40" rod w/RLS cap& Ced.Post w/loc.tag(in N-S fn. line).		
12" Cedar	N10°W	27.6	9" Cedar	N50°W	11.3
15" Cedar	N57°E	55.7	6" Cedar	S20°W	19.8
Ctr. of old over-grown E-W 4-Rod rd.					
Due S	8'±5'				

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-9 Recovered Sec. Cor. per one G.Johnson Wit. and one USBT Stub, burnt & lying down, showing lower face. Fd. Ir. & pointed post bottom.
I-8 Fd. Ir. that fits G. Johnson Wit.
1 Estab. 1/8 Cor. per Std. B.L.M. instructions.
2 Established 1/8 Cor. mid-way & on line between 1/4 Cor. W & Sec. Cor. E.
* Estab. NW Cor. of § 1/2-NW 1/4-SW 1/4 of Sec. 21 per Std. B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9			I-8			1		
Fd. 1 1/4"X3/8"X36" iron; added DNR Mon.&Ced.Post			Fd. 3/8"X1 1/4" iron, buried 15", in ctr. N-S bit rd; raised with 1/2" X 15" pipe			Set 5/8"X40" rod w/RLS cap & Ced.Post w/loc. tag		
6" Cedar	N55°W	17.4	5" W.Oak	N45°W	50.3	3" Tamarack	N10°W	38.6
5" Cedar	N05°W	11.7	9" B.Oak	S55°W	47.2	8" Tamarack	N72°E	73.2
6" Cedar	N70°E	21.7	Set Ced.Post w/loc.tag			9" Tamarack	S30°W	11.6
				Due W	33'	E-W Swp.Rd	Due N	10'
						E-W Rand	Due N	9'

SIGNED BY Carl F. Roser 5-15-78 DATE _____

STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR NO. 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE _____

(SEAL)

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET