LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N., R. 12 W.	D-5; E-5; F-5
2. PROPERTY CONTROLLING IN SECTION 17	T. 18 N., R. 12 W.	1
3. MISCELLANEOUS PROPERTY IN SECTION 17	T. 18 N., R. 12 W.	* 656'W. of #2(Sec. 17) &656'E. of D-5

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 4, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on April 26, 1977, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

1			*		
Set 5/8"X40" rod w/RLS Cap & Ced.Post w/Loc. Tag			Set 5/8"X40" re-rod w/RLS Cap & Ced. Post w/Loc. Tag		
6" B.Oak	ND5°W	11.0	10" Cedar	N25°W	18.5
5" W.Pine	N60°E	87.5	5" Cedar	N20°E	19.0
E-W rand.	Due S	0.3	Ctr.old E-W Rd.		
Ctr. crooked E-W trail	Due N	76'±		Due S	55'
			Ctr. of Rv.	Due W	507'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-5 Re-estab. 1/4 Cor. per std. B.L.M. instructions. Corner of smooth wire on trees is 50'± S. & 92'±W.

E-5 Re-estab. Sec. Cor. by Double Proportion to U.S.

F-5 Re-estab. 1/4 Cor. per Std. B.L.M. instructions.

1 Estab. 1/8 Cor. per Std. B.L.M. instructions.

* Estab. NW Cor.-E 1/2-W 1/2-NE 1/4 of Sec. 17 per Std. B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5			E-5			F-5		
Set DNR Mon. & Ced. Post			Set DNR Mon. & Ced. Post			Set DNR Mon. & Ced.Post		
4" Cedar	N70°W	7.3	5" Cedar	N40°W	16.1	9" Cedar	N65°W	10.5
5" Cedar	N45°E	11.7	7" Cedar	N75°E	2.5	9" Cedar	N10°E	32.2
4" Cedar	S50°E	17.5	8" Cedar	S80°W	8.6	5" Cedar	S40°E	16.5
Ctr.old E-W Rd.						E-W Rand	Due N	2.0
	Due S	45'±				N-S RR Grade	Due W	42'
W'ly edge of Rv.						3' Wide Streamflowing		WSW
	Due E	136'±					DueS	75'
E-W Rand.	Due S	0.6						

SIGNED BY Carl F. Roser 5-15-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET