LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N. S., R. 12 E. W.	F-7;
2. PROPERTY CONTROLLING IN SECTION 20	,T. 18 N. S., R. 12 E. W.	5; 7; 13
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on September 7, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~Description of original monument and accessories and/or subsequent restoration:~~

C. (continued) 13

Fd. 1 1/4" pipe in old E-W fn,
added 5/8"X40" re-rod & Ced.Post w/loc.tag

5" B.Oak	S07°E	82.2
4" B.Oak	S25°W	75.7

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-7 Re-established 1/4 Cor. equidistant & on Line between recovered Geo. Johnson Sec. Cor's. to E & W.

5 Restored N 1/8 on N-S 1/4 line, Sec. 20, from two G. Johnson wits.; said corner falling on straight line N-S 1/4 line & being in line with old fn. to E ±2'.

7 Fd. 1/4" rod in old 3/4" pipe at Cor. fence post, fn's W&N. Fits Geo. Johnson Wit. per his survey of E 1/2 of Sec. 20, dated 1931.

13 Fd. 1 1/4" pipe in old E-W fence for ctr. of SE 1/4, Sec. 20, per Geo. Johnson survey of E 1/2 Sec. 20, dated 1931.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-7

Set DNR Mon. & Ced.Post

12" Cedar	N40°W	60.1
8" Cedar	S02°E	86.3
4" Cedar	S20°W	66.2
Fd. 1" pipe	S80°W	89.1

Ctr. of old over grown E-W 4-rod Swp. Rd.
Due S. 14'±5'

5

Set 5/8"X40" iron rod in ctr. N-S rd.

8" Cedar	Due W	27.6
14" Hemlock	S75°E	39.5

Set Ced.Post w/loc.tag
Due E 33'
Fd. 1/2"X8" pipe (removed same)
N00°16'W 8.7

7

Fd. 1/4" rod in old 3/4" pipe added 5/8"X40" rod w/RLS cap & ced.Post w/loc. tag

6" Cedar	S30°E	5.2
5" Cedar	S20°W	3.7
Fn.Cor.(W&N)	Due E	28'
Ctr.stream	Due N	211'

SIGNED BY Carl F. Roser 5-15-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR
(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET