LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N. S., R. 12 E. W.	I-9; I-10
2. PROPERTY CONTROLLING IN SECTION 22	,T. 18 N. S., R. 12 E. W.	1; 14
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 6, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original corner and accessories and/or subsequent restoration~~

C. (continued) 14

Fd. 3/4" Pipe, raised w/1/2"X14"
pipe; in ctr. N-S bit rd.
7" Tw.W.Oak N55°W 49.8
10" W.Oak N50°E 55.7
Set Ced.post w/loc.tag
Due W 33'
Fn.remains w'ly Due N 66'±5'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-9 Recovered & accepted old corner of record, Hazelton & G.Johnson 1916, F.Jones 1935, G.Blass RLS and C.Cole RLS.
I-10 Recovered county road commission corner of record; from three of their Wits.
1 Recovered 1"X16" round solid Ir. by Geo. Johnson in 1916. Fits single proportion position.
14 Recovered old corner of record; G.Johnson 1916.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-9

Fd. 1/4" X 1 1/4" iron bar raised w/1/2"X15" pipe in ctr.rd. inter.
14" B.Oak N60°E 60.72
17" B.Oak S50°E 43.83
25" B.Oak S85°W 33.66
Set Ced Post w/loc tag beside fd. iron Due W 33'

I-10

Fd. 3/4" pipe, raised w/1/2X7" pipe; in ctr rd. inter.
12" Tw.B.Oak N67°W 88.4
22" W.Pine S35°E 74.8
11" B.Oak S40°W 92.4
Set CedPost w/loc.tag
Due E 33'

1

Set 5/8"X36" rod w/RLS cap & ced.post w/loc.tag
8" Cedar S40°E 54.6
7" Cedar S32°W 41.8
Ctr. of old over-grown E-W 4-rod Swp. rd
Due So. 1'(±5

SIGNED BY Carl F. Roser 5-15-78 DATE _____

STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET