LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 18 N. ~~S.~~, R. 12 ~~E.~~ W.	F-11; G-10; G-11
2. PROPERTY CONTROLLING IN SECTION 28	,T. 18 N. ~~S.~~, R. 12 ~~E.~~ W.	5; 7
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on June 20, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories required to perpetuate:~~

C. (continued)

5

Set 5/8"X40" rod w/RLS cap
& ced.post w/loc.tag

3" B.Oak	S30°E	10.0
3" B.Oak	S35°W	9.0
E-W Rand.	Due N	8.0
℄ Trail S'ly	Due E	21'
E-W Rand	Due N	8.0

7

Set 5/8"X40" rod W/RLS cap
&Ced.Post w/loc.tag

3" Maple	S65°W	69.9
8" Oak	N75°W	80.7

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-11 Fd. 3/4" Iron rod (buried) in E-W sand road. Iron fits Blass Wits.

G-10 Recovered Iron surrounded by stones (buried) that fits Blass data.

G-11 Fd. U.S.F.S. Conc. Mon., buried in road intersection. Above Wits. are to U.S.F.S. Spks.in trees.

5 Re-stored NE Cor. of S 1/2-NW 1/4 of Sec. 28, per un-recorded Sec. Sub'n., "Mary Will Sub-Division", as surveyed & layed out by R.L.S., Geo. Glass, in 1941. Also see B, item 2, Sec. 28, Code 3.

7 Estab. 1/8 Cor. per std. B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11

Fd. 3/4" iron rod

12" W.Oak	N57°W	97.2
13" B.Oak	S25°W	36.5

Set Ced.Post W/loc.tag
Due N 33'

G-10

Fd. Ir. (buried) & raised w/1/2"X22" pipe

Power Pole	N30°W	28.27
6" B.Oak	N32°E	86.52
6" Scotch Pine	S50°W	67.52

Cor. in ctr. dirt rd.
E-W&S
Set Ced. w/loc.tag
N45°W 33'

G-11

Fd. 5"X36" Conc.Mon w/bass cap

8" W.Oak	N45°W	54.73
27" W.Pine	N40°E	114.27
18" B.Oak	S32°W	69.50

Fd. Post w/loc.tag
S45°E 46.6

SIGNED BY Carl F. Roser 5-15-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

CHERRY VALLEY TOWNSHIP
LAKE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET