STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			LAKE	COUNTY
		τ	18 N	R 13 ** W
DESCRIPTION OF CORNER	East 1/16 on South 1	ine - Section	12	
CORNER MONUMENT Set 1	x 30" pipe, buried 6			
DATE MONUMENT PLACED AND	WITNESSED XX 6-	30-72		
WITNESSES TO CORNER	7" B. Oak	N 56 V	67.9'	
N	7" J. Pine	n 05 w	45.5'	
) 12	Set cedar post & location tag	Due N	33'	
	AND CL E-W rd.	Due N	2'	
CIRCLE CORNER REGISTER	ŒD			· · · · · · · · · · · · · · · · · · ·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner established by proportionate measurement.

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR 12028

7_7_70

Forestry Division, Lansing