STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			LAKE	COUNTY
		τ.	18 N	R _ <u>13</u> W
DESCRIPTION OF CORNER _	South 1/4 corner	, Section 11		
CORNER MONUMENT Fd. 2"	x 10" pipe & sto	me with cut-cross.	Added DNR	
DATE MONUMENT PLACED AND	WITNESSED	6-28-72		buried 10".
WITNESSES TO CORNER	8" J.P.	\$ 50 W	50.01	
N	8" Oak	N 10 W	90.5	
)11	18" Oak	N 43 F.	96.2'	
	AND Conc. Cor.			
V L	Fn. Post	S 10 W	36.1'	
CIRCLE CORNER REGISTERS	D.			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found recovered Blass corner of record. Corner falls in approximate center of E-W gravel road.

SES A SES	CARL F. ROSER LAND SURVEYOR No.	0.7
7. (H)	LAND SURVEYOR No. VEYORUSSFA	0

SIGNED

REGISTERED LAND SURVEYOR 12028

DISTRIBUTION: REGISTERED LAND SUI

Forestry Division, Lansing