

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


LAKE COUNTY  
T 18 N R 13 W

DESCRIPTION OF CORNER SE corner - Section 12

CORNER MONUMENT Found 2" x 2" x 2' angle iron. Added dept. monument, buried 8'

DATE MONUMENT PLACED AND WITNESSED 6-30-72

WITNESSES TO CORNER.....	BEARING	DISTANCE
Spike in 7" Oak	N 36 E	82.58'
13" J. Pine	N 50 W	93.3'
10" J. Pine	S 70 W	85.3'
Power Pole	S 43 E	49.3'
CL N-S rd.	Due E	2'
CL E-W rd.	Due N	3'
AND Set cedar post & location tag	N 45 E	50'



CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**Recovered existing corner from survey of record.**



SIGNED

*Carl F. Roser*

DATE

7-7-72

DISTRIBUTION:

REGISTERED LAND SURVEYOR

Forestry Division, Lansing