LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 19 N., R. 11 W.	C-11; D-11; E-11
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION 32	T. 19 N., R. 11 W.	ZZ (324.34 E of D-13 & 2,270.34 W of E-13)
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 28, 19 76, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on May 17, 19 76, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and or subsequent restoration~~

C. (continued)

ZZ
Set ½"x3/8"x18" iron & cedar post w/loc. tag
12" B. Oak S50°E 20.93
9" B. Oak S35°W 9.42

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-11 Found ½" pinch pipe in center of old abandoned E-W road grade. Recovered corner fits two witnesses by R.L.S. E. Benkert, fits small parcels to E on N side of road and fits distance ½ mile E & 1 mile W reasonably well.

D-11 Found pointed stake bottom and 13"x4"x20" stone and one witness as called for by previous George Johnson survey.

E-11 Found 1"x36" pipe as recovered by George Blass in 1963. Fits previous survey by George Johnson.

ZZ Established the SW corner of E 3/4 of SW¼ of SE¼ of Section 32; on south line of SE¼ Sec. 32 and 324.34; N89°24'40"E of S ¼ Section 32.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11
Found ½" pipe & added DNR monument & cedar post
4" W. Pine N75°W 65.1
5" W. Pine S60°W 28.8

D-11
Fd. pointed granite stone & added 1¼"x20" round iron
7" W. Pine S55°E 70.85
6" W. Pine S27°E 85.12
17" R. Pine S60°W 99.69
Set cedar post w/loc. tag
N45°W 66

E-11
Found & accepted 1" pipe
27" W. Pine S35°E 73.1
7" W. Pine S75°W 81.93
Set cedar post w/loc. tag beside found iron, which is
Due N 40

SIGNED BY Carl F. Roser 4-28-77 DATE

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

ELLSWORTH TOWNSHIP
LAKE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET