Tansing-Forestry

## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
I. PUBLIC LAND SURVEY		G-13; H-13; I-13	
2. PROPERTY CONTROLL-34_		_15	
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. R E. W.		
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Carl F. Roser  do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 6-7  1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX			
C. continued:	Code 15		
Set 1"x36" pipe, buried 11" Ironwood S86W 45.85			
17" Sugar Maple N44W 61.37			
W 1/16 on N line 3 Due E 13.96 Set Ced post w/loc tag Due E 33'			
Ctr N-S Gravel Rd Due W 3'±			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
Reestablished corner pre standard B.L.M. instructions.			
Restored corner from two USBTs, white Pine stumps, which fits location of broken down cor. fence, fence mostly down E & N, 33't North.			
Reestablished corner per standard B.L.M. instructions.			
Established corner per	standard B.L.M inst is due N 22'±. Bol or corner and accessories  OST Set DNR Mon. 68.8 14" R. Oak 14.0 6" Maple 18.9 N Sec. 3	ructions. Fn remains t buried in rd, possis established to perpetuate lo H-13 . & Ced. Gd. Post S N65W 16.3 9 N33E 25.3 7	to the West are due S. Libly by Johnson, N32°30'W cating the position of the corner,  I-13 et DNR mon & Ced Gd Post "R. Oak N 8E 18.3 "R. Oak N40W 9.4 for to Secs 2&3 Due E 30.21
SIGNED BY Carl, 7.  SURVEYOR'S MICHIGAN REC	Cokil GISTRATION NO1	DATE	OF MICHAIL OF MICHAIL OF MICHAIL OF CARL
FOR STATE AND UNITED ST		DATE	LAND LAND
APPROVED AND SIGNED BY	MICHIGAN REGISTERED	LAND SURVEYOR DATE	No. 12028
			WIND TAND STAN

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28 1971 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SUPPLEYSME.

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_\_

Form No. ML M736

G-13

H-13

I-13

15