LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	İ
L PUBLIC LAND SURVEY	19 N. R. 12	H-8; I-8	
2. PROPERTY CONTROLL- ING IN SECTION	22 , _{T.} 19 , N. 12 .	14	
A MICCALL AND STOR	22 ,T. 19 N. R. 12 P. § 658.71	-	 8
	RECORDED PLAT		
5. PRIVATE CLAIMS		·	REGISTER OF DEEDS STAMP

Carl F. Roser do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on. December 9, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on December 9 1974, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of

э)- =]] се ча і і қ і не э қ эн і і і не је не пениян эне дам же в ям іск- вині эк ченра ефиса с се мови в не

C. (continued)

	XX				
Set railroad	spike in	b-top road			
20" Maple	N15°E	141.50			
5" J. Pine		66.96			
Cedar post w/loc. tag					
	Due W	331			

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- Established center of Sec. 22 (in swamp) at intersection of 4 lines, which fits old H-8 line fence to east (out of swamp).
- Recovered C. Cole's 4-3/8"x3/8"x19" rod, in approximate center of N-S blacktop road I-8 and in line with fence west.
- Established corner per standard B.L.M. instructions. 14
- Set NE corner of SE-SE-SE of Sec. 22 per standard B.L.M. instructions. XX

C. Description of monument for corner and accessories established to perpetuate locating the position of th

11 0	to perpetuate to eating the position of the corner;			
II-8	F.1. I-8	14		
Set 1"x6' pipe & cedar post w/loc. tag	011 4	Set railroad spike in b-top road		
8" Ash N50°W 22.6		30" Oak N62 ⁰ W 75.65		
4" Maple N55°E 27.4	1100 11 31.72	5 merry Bue n 45.05		
70. 0.1	Center blacktop road	Loc. tag on corner fence post		
7" Cedar S80 W 31.6	Due W 5 t	Due E 33'		

SIGNED BY. SURVEYOR'S MICHIGAN REGISTRATION NO. 12028	CARL F. ROSER LAND SURVEYOR
FOR STATE AND UNITED STATES AGENCIES:	12028
SIGNED BY. CHIEF OF SURVEY PARTS DATE	TO LAND Some
APPROVED AND SIGNED BY. MICHIGAN REGISTERED LAND SURVEYOR - DATE DATE	·

AND

SOUTH NEWKIRK TOWNSHIP LAKE COUNTY