## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

		•			
For Corners In: Lake (County)	Loca	ited In	Corner Code #		
1. Public Land Survey	T 19/		A9		
Property Controlling in Section	T <u>19</u> 1 S T T	R 13W R R R	M9		
Miscellaneous     Property in Section	s T	R		Register of De	eds Stamp & File Number
4. Lot No:	Recorded Plat: _		<u>.</u>	A B C D E F	G H I J K L M
5. Private Claims:				2 - 6 - 5 - 4	
I, <u>Craig W. McVean</u> , in a frequirements of PA 74, Min and 2 above were in conforthe current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board of established, re-established.	chigan PA of 1970, the mance with regulation over instructions of the anagement or by a decilines 3, 4 and 5 above of Land Surveyors or	e corner points as and rules the e United State aree of a Court of were in confor by a Decree	mentioned in lines 1 erefore as required in s Department of the of Law and/or that the mance with the rules of a Court of Law;	3 4 - 7 - 8 - 9 5 6 - 18 - 17 - 16 7 8 - 19 - 2021	-10
NOTE: Not more than be recorded on this ce		e same town	and range, may	10 30 -29 -28 11 12 -31 -32 -33	35 36
A. Description of original monument and accessories and/or subsequent restoration:  A9 & M9 - GLO - Set post - S. Sibley - 1838 Pine 6" N21°W 84 L. Pine 6" S14°W 68 L.  GLO - T19N, R12W Sub S. Sibley - 1838 Corrected E. from corner.  Old Co. sur. notes (L. S. Cobb - 1878?) Thunder Mug filled / bottles & glass for corner.  F. Jones Bk 1930's - 1878- A thunder mug filled with bottles for corner. Witnesses gone -1908.  ACRC - L. 2, P. 107 - C.F. Roser - 1973 Recovered 2 - Fn. Post irons 2' long from Geo. Blass witness. Added DNR Mon. buried. P.P. N27°W 41.30'; 18" B. Oak S35°E 65.86' 14" B. Oak S55°W 66.83; Ctr. Sand Rd. S. Due W. 4' Ctr. E-W Sand Rd. N 13'.  - LCRC - L. 3, P. 76 - C.F. Roser - 1988 Fd. DNR Mon same wit. as L. 2, P. 107					
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:  A9 & M9 - Standard Sec. corner common to Sec. 19 & 30, T19N, R12W and Sec. 24 & 25, T19N, R13W -  Excavated Sand Rd. 'T' intersection w/ Robert Wetherell, PS #24624. Find broken thunder mug  (Crockery night commode) with one small bottle buried in intersection as per old Co. Surveyor notes.  CL on Sand Rd. S is 3' E. CL of E-W Rd. is 8' N. Broken thunder mug accepted as the best available evidence of the position of the original corner.					
Reference Pt. 'C' – Fd. broken DNR Alum. cap on 1" x 27" iron pipe w/ 2- 30" long iron fence post on either side per Roser LCRC's–S49°18"E 9.57' of A9 & M9. Position used by Blass to set A10 - M10 by single proportion. Position used by Roser to prorate & set corners to the East. Broken DNR Monument & fence post irons not utilized as A9 - M9 in this survey. Replaced broken DNR Mon. w/ cabin spike & reset fence post irons on either side.					
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  A9 & M9 — Replaced broken thunder mug w/ 4" DOC (DNR)  Brass cap on 1" x 36" Galv. Iron pipe w/ cap encased w/ conc. — Down 1.5'.  Placed all broken crockery at base of monument as memorial.  N59°W 75.90' to set N & T in SW side 7" J. Pine scribed 'XBT'  N69°E 85.69' to set N & T in NW side 8" W. Pine scribed 'XBT'  S38°E 75.21' to set spike & tag in NE side 28" B. Oak (CFR)  S45°W 64.67' to Fd. nail in NW side 20" B. Oak (CFR)  N19°W 34.09' to set N & T in W side PP  N 33' to reset Cedar post w/ loc. tag & set Blue Carsonite Post w/ Loc. tag  S49°18'E 9.57' to cabin spike & fence post irons — Reference Pt. 'C'.					
Signed by:	ray W.	me?	l'em-	Date	11/26/2001
Surveyor's Michigan I	License No.:	39088			. ,