## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 19 N.R. 13 W

			<del></del>	LAKE	
DESCRIPTION OF CORNER	1/4 corner	common to Sec	ctions 13 - 14		
CORNER MONUMENT	Found 3/4"	pipe. Replac	ced with Standard De	ept. Monument	
DATE MONUMENT PLACED A	ND WITNESSED	November 1968	3		
WITHESSES TO CORNER	• • • •	<u> </u>			
N		9" J. Pine	S 40 W	35,3	!
1	AND	4" Oak 18" Oak	N 40 W N 10 E	51.7 46.9	
CIRCLE CORNER REGISTERE		6" Oak	\$ 75 E	41.3	•

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered by George Blass in 1941.

SURVEYOR'S SEAL

SIGNED ( CON T. ) ORCE

REGISTERED LAND SURVEYOR (LOCAL)

OR #12028