LAND CORNER RECORDATION CERTIFICATE

uirement of Act 74, Mich. PA 1970

	Filing Re	quirement of 7 oct 1 17 mass	
For Corners In:	Located In	Corner Code #	
(County)			
1. Public Land Survey	T <u>19N</u> R <u>1</u> T R	3W <u>I-9</u>	
Property Controlling in Section	S T R S T R		
Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number
requirements of PA 74, N and 2 above were in con the current manual of s Interior, Bureau of Land N corner points mentioned of the Michigan Board established, re-established	field survey on June 19, 2001 of Michigan PA of 1970, the corner formance with regulations and ru urvey instructions of the United Management or by a decree of a fin lines 3, 4 and 5 above were in of Land Surveyors or by a Died, monumented, recovered, found an 2 corners, all in the same certificate.	do hereby state that under points mentioned in lines 1 les therefore as required in States Department of the Court of Law and/or that the conformance with the rules ecree of a Court of Law; d as expressed below:	A B C D E F G H I J K L M 2 - 6 - 5 - 4 - 3 - 2 - 1 3 - 4 - 7 - 8 - 9 - 10 - 11 - 12 6 - 18 - 17 - 16 - 15 - 14 - 13 7 - 8 - 19 - 20 - 21 - 22 - 23 - 24 9 10 - 30 - 29 - 28 - 27 - 26 - 25 11 12 - 31 - 32 - 33 - 34 - 35 - 36 13
	inal monument and accessorie	es and/or subsequent restora	ation: : – L. 2, Pg. 54 – R.A. Griffin – 1972 – in 1966 Fd. w
	~ ~	20,10	FIOT boot colko I DIS COIII

1-9 - GLO- Set Post S. Sibley- 1838

Pine 30" S13°E 43L.

Pine 12" N57°W 43L.

- L.S. Cobb- 1878

Y. Pine 20" N621/2°E 111 L. W. Pine 16" S481/2 °E 41L.

- R.H. Hollister –1905

found old witnesses & set stone at this corner.

- G.H Johnson - 1925-Stone

- B. Oak 10" S78°E 48.2 B. Oak 18" N75°W 64
 MDOT- 1930 Proj. M043-12 15.3' Rt. Sta. 289+70- Stone N53°E 79.3' Bent Spike in 12" Tw. Oak N73°W 64.1' Bent Spike in 14" Oak S60°E 48.1' Bent Spike in 12" Oak
- G. Blass -1952 Stone from highway Survey of 1932 removed placed Old wagon sheave (axle) from highway wits of 1932

 18" B. Oak N73°W 64.10' (OBT) 8" W. Oak N33°E 57.00'

 14" B. Oak S60°E 48.10' (OBT) 12" W. Oak S44°E 51.55'
- gon Skein raised to surface with 5/8" sq. boat spike. This corner is 14.8' E of apparent C/L M-37. Fd Stp. of One of Cobb's BT's both Johnson BT's, 3-MDOT BT's & 4 Blass BT's in agreement w/ skein. Replaced wagon Skein w/ 5" sq. X 3' Long conc. post w/ 3" Brass Cap (stamp) 10" dock spike in the SE side 5" Maple scribed 'BT'; N56°E 91.35'; 10" dock Spike in SW side 7" W.
 Oak scribed BT. S51°E 110.53'; W 66' Metal USFS post X cut in top of a stone (2.5' long X 1.8' wide X 0.8 up) N37°W 125.74'
 -LCRC – L. 3, Pg. 52 – C.F. Roser – 1988- Fd. F.S. capped

conc. mon.- buried 1' - fit 3 USFS wit & 1 Blass wit. 6" Maple N55°E 91.35' 9" W. Oak S50°E 110.53'

'X' on top 2.5' X 2' stone N40°W 125.7' C/L M-37 W 15' C/L Dirt Rd. E - due S. 9'

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- 1-9 Sec. corner common to section 22, 23, 26, & 27 found 3" USFS brass cap (properly stamped) on concrete post in mon. box – 14.8' E of apparent curve C/L of M-37 at position perpetuated by Cobb, Hollister, Johnson, MDOT, Blass, Griffin & Roser. USFS Mon. accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

1-9 - USFS Brass Cap conc. Monument in mon. box N45°E 50.00' to set Blue carsonite post with location tag
West 66' to Fd. steel post with USFS tag (RAG)
S52°E 110.57' to Fd. spike in SW side 12" W. Oak (RAG,CFR)
N55°E 91.45' to Fd. spike in SE side 7" R. Maple (RAG,CFR) N40°W 125.22' to Fd. Chiseled 'X' on top 2.8' X 1.8' X0.9' (up) Granite stone (RAG,CFR) N33°E 57.60' to set N&T in W. side 14" W. Oak (GB)



Signed by: Cray W. 1	Me Vem	Date /1/26/2001
Surveyor's Michigan License No.:	39088	