

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
 Lake _____ Located In _____ Corner Code # _____
 (County) _____

1. Public Land Survey T _____ R _____
 T _____ R _____
 2. Property Controlling in Section S 14 T 19N R 13W 9
 S 14 T 19N R 13W CSNE1/64
 3. Miscellaneous Property in Section S _____ T _____ R _____
 S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on March 7, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

9 - G. Blass - 1960 - Survey of Sec. 14
 Set 1/2" iron pipe

C-S-NE 1/64 - G. Blass - 1960 - Survey of Sec. 14
 Set 1/2" iron pipe

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

9 - C-E 1/16 Cor. Sec. 14 - Fd.
 1/2" I.D. Iron pipe per Blass Survey.
 1/2" iron pipe accepted as the best available evidence of the position of the corner

C-S-NE 1/64 - SE cor. of N 1/2 of SW 1/4 of NE 1/4 of Sec. 14 -
 Fd. 1/2" I.D. Iron pipe per Blass Survey.
 1/2" iron pipe accepted as the best available evidence of the position of the corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9 - 1/2" Iron pipe
 E 1' to set Blue carsonite post w/loc. tag
 N82°W 11.21' to N&T in N side 3" J. Pine
 S5°E 21.33 to N&T in E side 4" J. Pine
 N55°E 36.41' to set 1/2" x 24" Rebar

C-S-NE 1/64 - 1/2" Iron pipe
 NE 1' to set blue carsonite post w/ loc. tag
 S15°E 19.35' to N & T in E side 5" J. Pine
 N88°E 24.89' to N & T in N side 8" W. Oak
 N24°E 14.03' to N & T in W side 14" B. Oak
 N82°W 15.77' to N & T in N side 6" J. Pipe



Signed by: Craig W. McVean
 Surveyor's Michigan License No.: 39088

Date: 11/26/2001