LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 20 N., R. 11 W.	E-13, H-13
2. PROPERTY CONTROLLING IN SECTION	33, T. 20N N., R. 11 W.	14
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N., R. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on MARCH 5, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (CONTINUED)

14

FD OLD 3/4" PIPE; ADDED
CED POST W/LOC TAG.
5" MAPLE N50°E 18.3'
10" MAPLE S20°W 20.1'
9" MAPLE S60°W 28.9'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-13 FD OLD 1" PIPE - HAZELTON, BLASS & COLE HAVE USED THIS COR FOR SE OF SEC 32. G.H. JOHNSON USED THIS COR FOR SW OF SEC 33, BUT MAY HAVE ALSO USED IT FOR NW COR OF SEC. 4 (T19N R11W). THIS SURVEYOR ACCEPTS THE 1" PIPE FOR COR COMM TO SEC'S 32 & 33 ON SO LINE OF T20N R11W. FD 1/2" ROD WITH D.WOOD RLS CAP #24625, S88°11'E 50.11' (U.S. = 50.2') WHICH WAS SET FOR NW COR OF SEC 4 (T19N R11W; THIS COR APPEARS TO BE 1.8' TOO FAR NORTH OF S LINE OF T20N R11W.

H-13 FD 3/4" IR ROD IN LINE WITH N-S FENCE TO NORTH.

14 FD 3/4" PIPE & 2 G.H.JOHNSON 1928 WITS FOR SE COR OF NE-SE OF SEC 33. COR IS IN OLD N-S FENCE. NEWER N-S FN IN TREES IS 2'(±3') EAST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13

FD OLD 1" PIPE W/ 3"X4" FLANGE.		
CTR 7"X7" BELL TX RISER	N20°W	68.5'
*POINT ON TOP 4 1/2'X 3' ROCK	N65°E	69.0'
9" W PINE	S25°W	65.55
SET CED POST W/LOC TAG BESIDE FD IRON	S85°E	50'
CTR N-S BIT RD	DUE E	13'±

*FD G.H. JOHNSON WIT

H-13

FD 3/4" PIPE.		
APPROX CTR 2 1/2X 3 1/2' ROCK	N30°W	24'
APPROX CTR 2 1/2X 2 1/2' ROCK	N50°E	39'
COR FN POST	DUE N	29.68
N 1/4 S 3 T19N R11W	N89°59'E	55.41
CTR E-W DIRT RD	DUE S	10'
SET CED POST W/LOC TAG	DUE N	33'

SIGNED BY Carl F. Roser 4/07/84 DATE

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

DOVER TWP
LAKE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET