Profession . . .

REMONUNI

LAND CORNER RECORDATION CERTIFICATE

For corners in Lake		ement of Act 74, Mich. P.	.A. 1970	REC	SEP	LAKE
(County)	Located In:	Corner Code ##	-	SIS.	~	O O
Public Land Survey	T 20N R 12W T R R T R R	LIDER OO3 PAGE O	37և	REGISTER OF DEEDS	3 11 PH 19	COUNTY, MI.
	T R		9 , 4	0, 0	क्र	
	T R				**	
	TR TR		Register o	f Deeds Stam	p & File I	Number
4. Lot No, Record			<u>A</u>	BCDE	- G н	1 J K L
5. Private Claims			2		3	2
			3			
		· 105	- 4		10	
1, in a	field survey on	August 20, 96				
do hereby certify that under requirem	ients of P.A. 74, Michigan P.A				5——15—	14-1-1
in lines 1 and 2 above were in confi current manual of survey instruction	•	-				_
Management or by a decree of a Cour	d of Law and/or that the corn	er points mentioned in lines 3, 4 :	and 5 8	9202	122	23—2
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			e of a		\perp	- - -
expressed below:	abhanea, monamemea, re-	monumented, recovered, loan	10] 30——29——2	327	262
NOTE: Not more than 4 corner	s, all in the same town a	nd range, may be recorded	11		_	
on this certificate.			12	32 3	3——34—	353
			13			<u> </u>
A. Description of original monu 1-13 - Section corner common	ment and accessories an n to Sections 34 & 35. T2	d/or subsequent restoration ON. R12W. North Nevkirk Twp	: ., Lake Co., Mi.			
1838 - J. Hodgson, G		– George Johnson (1920's m		- 4 - Carl Roser	, LS 1202	<u>:8</u>
#1 - 20" Hemlock N36		in Road		R.C Liber		
#2 - 10" Hemlock N42		' W Ash NW 25'		covered 1-1/4		ossible
(Closing corner 78 L		' W. Ash NE 11'	G.	Johnson witne	ess"	
		Maple N77 ⁰ W 43.6				
		edar Post due West 16-1/2' enterline North and South Bi	t Road-Fast 1	ξ1		
		W. cor. Sec. 2 East 51.48'	e. Nodu Edd I.			
B. Description of corner eviden <u>I-13 - Section corner commo</u>						
I found a 1-1/4" pip at 51.65'.	e 15 feet West of the cer	nterline of North and South	blacktop road.	Found closing	g corner 1	to East
	essories are as follows: ound in good condition,	#1 Gone, #2 Gone, #3 Gone,		ne, #6 Found (down, #7 i	ound in
HATIFIED BY THE LAKE CO. PEER F IN ACCORDANCE WITH P CHAIRMAN CA DATE S	1.35 W.					
C. Description of monument for 1-13 - Section corner commo					ner:	
		Brass Cap inside of the for	and 1-1/4" pipe,	and is accept	ted as a	careful
	blishment of the position 10' ((60d spike in N. sid				<u> ھىرى .</u>	de Coleman.
	,				. 4804	AAAAAAAAAAAAAA A

ROBERT L. WETHERELL LAND SURVEYOR NO. September 5, 1996 FORM APPROVED BY MICHIGAN STATE BOARD OF LANS SURVEYURS. 24624 _ Date ___

Surveyor's Michigan License No.

Signed by .

8" Tw. Apple $$33^{\circ}W$ 38.84' (60d spike in W. side) 4" Tw. B. Oak $$N55^{\circ}W$ 22.7' (60d spike in S. side)

Centerline North and South blacktop road East 15' #7

Brass Cap Iron (Sec. cor. 2 & 3, T19N, R12W) East 51.65' #8

OF MICHIGAN