## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Requireme	ent of Act 74, Mich. P.A. 1970	
LAKE (County)	Located In:	Corner Code ##	
Public Land Survey	T 20N R 13N	K-9	
1. Fublic Land Survey	T R	M-8,	
•	T R T R		
2. Property Controlling		14, 15	•
in Section			
3. Miscellaneous Property in Sec.		Reg	ister of Deeds Stamp & File Number
4. Lot No	Recorded Plat		
			A B C D E F G H I J K L
			3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
8481 T W. 1844 A	•		4 7 8 9 10 11 12
do hereby certify that under re in lines 1 and 2 above were current manual of survey inst Management or by a decree o above were in conformance w	, in a field survey on JUNE 16 equirements of P.A. 74, Michigan P.A. of 197 in conformance with regulations and rule ructions of the United States Department I a Court of Law and/or that the corner point the rules of the Michigan Board of Law re-established, monumented, re-monumented.	70, the corner points mentioned es therefore as required in the tof the Interior, Bureau of Landints mentioned in lines 3, 4 and 5 and Surveyors or by a Decree of a	5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificate	corners, all in the same town and rai	nge, may be recorded	11
· · · · · · · · · · · · · · · · · · ·	monument and accessories and/or s	•	13
K-9	, M-8	14	15 OF MICHIGAN
B. Description of corner of	evidence found and/or method applie	ed in restoring or reestablishing o	SURVEYOR  No.  33981  CONNECT:  CONNECT:
K-9	M-8	14	15
FD 1/2" PIPE FOR THE SW CC S-24 AS FD & RECORDED BY C.COLE IN 1977 (LI 02, PG 304). FD REMAINS OF AL C.COLE WITS, FIT GOOD. CT E-W SAND RD IS 3' NORTH. OF M-37 IS 326'+/- E.	BY G.BLASS IN 1966, MIDWAY & ON LINE BETW SEC CORNERS. CORL 3 FITS 1971 CERT OF SURVEY BY R OF G.BLASS (LI 1, PG 115 &	EAST LINE SEC 24 PER STANDARD R BLM INSTRUCTIONS. COR IS IN CTR N-S SAND ROAD.	ESTABLISHED THE SE COR OF
C. Description of monume	ent for corner and accessories establ	lished to perpetuate locating the	position of the corner:
FD 1/2" GALV PIPE.	FD 1/2" GALV PIPE IN CTR N-S	DR 5/8" X 34" REROD W/RLS CAP.	
8" J PINE N30"W 31.	SAND ROAD. 9' #12" B DAK N70°W #1.10'	13" DAK N50°W 39.8'	9° W DAK N25°N 28.8′
3" R PINE N25°E 41.			7" J PINE N30°E 34.2'
5° J PINE 510°W 38.			3" N PINE 550°E 55.1
6" N DAK S45°N 45. SET CED POST W/ LOC TAG. NORTH 33'	3' \$12" B DAK \$70°N 24.48' SET CED POST W/LDC TAG AT FD "I" IR N/RLS TAG. NEST 33'	SET CED POST W/LOC TAG. EAST 33'	9" N DAK S30°N 24.9' SET CED POST N/LOG TAG. SOUTH 33'
	**=RLS R. WETHERELL 1992 WIT.		
Signed bya	L 7 Kirkela	Dale 5-/	6-97
Surveyor's Michigan Licens			D BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 18