

MAR 23 2000

REMONUMENTATION

SECTION

For corners in	Filing Requirement of	COATION CERTIFIC Act 74, Mich. P.A. 19	CATE
Lapeer	Located In: Corner Code		RECEIVED FOR ACCORD
(County)	Located In: Corner Code Hadley Township	#	00 JAN 17 AM 9: 04
Public Land Survey Property Controlling in Section Miscellaneous	T6N R9E C-1 T R		REGISTER OF DEEDS LAPEER COUNTY, MICHIGAN
Property in Sec.	S T R		7
4. Lot No, Record	ed Plat		Register of Deeds Stamp & File Numb
Huston K. Kennedy in requirements of P.A. 74, Michigan P conformance with regulations and rule United States Department of the Interest.	a field survey on August 3, 1999 do he A of 1970, the corner points mentioned in lines a stherefore as required in the current manual of su or, Bureau of Land Management or by a decree of se 3, 4 and 5 above were in conformance with the	eneby state that under 1 and 2 above were in rvey instructions of the	2 6 5 4 3 2 1 3 K L M
Board of Land Surveyors or by a li recovered, found as expressed below.	Jeans of a Cont of the sample	e rules of the Michigan blished, monumented,	7
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		corded	9
			11 - 26 - 25 - 26 - 25 - 25 - 25 - 25 - 25
A Danielle Control	ment and accessories and/or subsequent		12 31 32 33 34 35 36
2.) 1998-Kennedy, PS # 3.) 1971-Kay, PS #1409 4.) 1973-Carlson, PS #9 B. Description of corner eviden 1999-Kennedy Surveying extending to the East & V	S.; Set Post 5" Thorn S29"W 29 Links; 3510; LCRC L.004, Pg.278 – Fnd a Ra 17623; LCRC for (C-13 Elba Twp.) L.C6; Survey L.001, Pg.44 – Fnd a Railro; 189; Survey L.002, PG.357 – Fnd a Roce found and/or method applied in restoring, Inc. – Kennedy, PS #17623 – Fnd a lest, which has a gravel surface. A old 32, T7N, R9E, Elba Twp. (C-13) is located the surface.	aitroad Spike 2006, Pg.0068 - Frik ad Spike aitroad Spike, and u ig or reestablishing co Raitroad Spike in th	if a ½" fron Rod sed same wit as 1989 LCRC (Con't on back side)
Witnesses from LCRC #1	, Survey #3 & 8 were used to recover	and verify the locati	on of the found Railroad Spike
I accepted the found Rail	road Spike as the best evidence of the	original comer pos	iton.
FIELD MEASURMENTS BE		•	
C-1 to B-1 No GLO No recorded distances 2651.23 Ft. (MEA 1998) C-1 to C-13 GLO = 82 Links or 54.12 Ft. 379.66 Ft. (MEA 1998)	C-1 to D-1 No GLO Recorded Survey by Harold N. 2632.05 Ft. (MEA 1998)	. Elrich, PS #18986 da	5 5 J 3 7 %
Remonumentation, #1762: Due South 32.30' Set Mag S26°W 30.45' Set Mag Na N33°W 37.45' Set Mag Na N55°E 85.05' Set Mag Nai	corner and accessories established to perpailroad Spike with a ½" x 24" Iron Rod 3 Nail & Remon Washer West face 11" Ash I & Remon Washer SW face 25" Mapl & Remon Washer SW face 27" Maple Remon Washer NW face 27" Maple mmon to Sections 31 & 32, T7N, R9E,	Elm e	PROFESSIONAL SURVEYOR 17623 position of the corner of the
The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the original corner.			
Signed by:	•		
Surveyor's Michigaen License No.	19623 WE	Date <u>/O -</u>	248

SURVEY & REMONUMENTATION

MAR 23 2000

SECTION

Town 6 North, Range 9 East, Hadley Township C-1

- 5.) 1977-Kay, PS #14096; Survey L.004, Pg.55 Fnd a Railroad Spike, used same wit as 1971 Survey
- 6.) 1977-Elrich, PS #18986; Survey L.004, Pg.291 Fnd a Railroad Spike, used same wit as 1971 Survey 7.) 1989-Gravlin, PS #23510; Survey L.008, Pg.204 Fnd a Railroad Spike, used same wit as 1989 LCRC

- 8.) 1990-Elrich, PS #18986; Survey L.008, Pg.622 Fnd a Railroad Spike
 9.) 1992-Brown, PS #24588; Unrecorded Survey Fnd a Railroad Spike, used same wit as 1971 Survey
 10.) 1995-Gravlin, PS #23510; Unrecorded Survey Fnd a Railroad Spike, used same wit as 1989 LCRC