

MAR 23 2000

REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE

| | Filing Requirement of Act | 74, Mich. P.A. 1970 | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|
| For corners in | | | |
| <u>Lapeer</u> (County) | Located In: Corner Code # Hadley Township | | RECEIVED FOR FECORD |
| 1. Public Land Survey | <u>T6N R9E L-1</u> T R | - - | 00 JAN 17 AN 9:06 |
| 2. Property Controlling | T R | | Melisse De Vauss REG! BEEDS LAPEER COUNTY, NICHIGAN |
| in Section 3. Miscellaneous Property in Sec. | S T R S T R | = (461) | |
| , ropolly in a ser | | Registe | er of Deeds Stamp & File Number |
| 4. Lot No, Records 5. Private Claims | ed Plat | 1 A B C 2 6 | D E F G H I J K M |
| | | 3 | +++++++ |
| requirements of P.A. /4, Microgan in conformance with regulations and rul United States Department of the Inte- that the corner points mentioned in li- Point of Land Surveyors or by a | a field survey on <u>August 5</u> , 19 <u>99</u> do here. A. of 1970, the corner points mentioned in lines 1 less therefore as required in the current manual of survivor. Bureau of Land Management or by a decree of innes 3, 4 and 5 above were in conformance with the Decree of a Court of Law; established, re-established. | rvey instructions of the a Court of Law and/or 6 19 | 20 21 22 23 24 |
| recovered, found as expressed below | | 9 | |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded | | | 29-1-28-1-27-1-26-1-25-1 |
| on this certificate. | | 11 | 33 34 35 36 |
| | nument and accessories and/or subsequen | 12 31 | |
| 4.) 1995-Flint Surveyi B. Description of comer eving 1999-Kennedy Surveyi Road extending to the comer of Section 36, 1 town line. | witnesses – Set a ½" Re-bar w/CHC ing; Unrecorded Survey – Fnd a ½" Redence found and/or method applied in restoring, Inc. – Kennedy, PS #17623 – Fnd East & West, which has a gravel surfactor, R9E, Elba Township (L-13) is locative used to recover and verify the loc | ring or reestablishing corner: a ½" Iron Rod w/cap #9189 In toce, also a fence-tree row extend ted 211.76 feet to the East. L-1 | the existing centerline of Sutton ling to the South. South 1/4 as found is 0.59 feet South of the |
| | 1/2" fron Rod w/cap #9189 as the best e | | |
| FIELD MEASURMENT | | | . sathiteliae. |
| L-1 to K-13 | L-1 to M-1 | | .65 Ft. STANSFORM OF MICH. |
| No GLO No recorded distances 2639,49 Ft. (MEA 1995 | | nt Enginering dated 7/26/93 = 2638 | KENNEDY RENNEDY |
| <u>L-1 to L-13</u> No GLO 211.76 Ft. (MEA 1995) | 1 | | SURVEYOR 17623 |
| C. Description of monume L-1 I replaced the found Remonumentation, # N55°E 49.05' Set Ma S50°E 54.72' Set Ma S05°E 47.72' Set Ma S48°W 62.20' Set Ma S48°W 62.20' Set Ma | int for comer and accessories established to Jund ½" Iron Rod with a ½" x 24" Iron Ro 17623 In Nail & Remon Washer SE face 10" Washer NE face 12" Hay In Nail & Remon Washer West face 13" In Nail & Remon Washer NW face 10" In Nail & Remon Washer NW face 10" In Nail & Remon Washer NW face 10" | Valnut lickory Ash Walnut Elba Twp. (L-13) | My) - 9 G |
| The selected iscation is the position of the origin | accepted by me and is generally acce | epted by Professional Surveyor | |
| That | <u> </u> | Date//~ Z | 2-99 |
| Signed by:Surveyor's Michignan Lices | nse No. /7623 | | |
| Surveyor's Michignan License No. URER 0006 PARE 0254 | | | |