

MAR 1 3 1998

REMONUHENTATION

•••		RECEIVED TOR RECORD
SECTION	LAND CORNER RECORDATION CERTIFICA Filing Requirement of Act 74, Mich. P.A. 197	TE ,
For corners in	rung Requirement of Act 74, Mich. F.A. 191	97 NOV 12 PM 3: 14
Lapeer	Located In: Corner Code #	
(County)	Located In: Corner Code #	Malissa De Vough
1. Public Land Survey	T 6N R 10E N-3 T R Sea + 1/	REGISTER OF CEEDS LAPTER OF STATES TOWN
Property Controlling in Section Miscellaneous Property in Sec.	T_R_	Register of Deeds Stamp & File Number
4. Lot No, Recor	ded Plat	A B C D E F G H I J K L M
5. Private Claims		
	,	2 6 5 4 3 2 1
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the that the corner points mentioned	, in a field survey on $8/7$, 19 97 do hereby state that under an P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in d rules therefore as required in the current manual of survey instructions of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 1 in lines 3, 4 and 5 above were in conformance with the rules of the Michigan of a Decree of a Court of Law; established, re-established, monumented, elow:	4
	ners, all in the same town and range, may be recorded	9
on this certificate.	t e	10 30 29 28 27 26 25
		11
1817-GLO Carpenter, D.S. 1.) 1977-Henderson, PS # 2.) 1977-Bates, PS #1669 3.) 1985-Elrich, PS #1669 4.) 1987-Carlson, PS #918	onument and accessories and/or subsequent restoration: , Set Post 16" Sugar N68 W 13 Links; 6" Beech S30 W 38 Links #16043; Survey L.003, pg.957 - Fnd 1/2" Iron Rod in a Monument 199; Survey L.4, pg.390 - Object found not stated, used same wit 199; Survey L.6, pg.972 - 1/2" Iron Rod in a Monument Box, used same 189; Survey L.7, pg.539 - 1/2" Iron Rod in a Monument Box, used same 199; Survey L.10, pg.337 - 1/2" Iron Rod	as first recorded Certificate of Survey me wit as first recorded Certificate of Survey
1997 Kennedy Surveying, extending to the Not to the East & West, Sections 6 & 7, T6	idence found and/or method applied in restoring or reestablishing corn Inc Kennedy, PS #17623 - Fnd 1/2" Iron Rod in a Monument Borth & South, which has a gravel surface, and 1.70 feet South of the which has a bituminous surface. This corner is being used and N, R10E, Metamora Township (\lambda-3). Wey #5 were used to recover and verify the location of the four	ox in the existing centerline of Baldwin Road he existing centerline of Pratt Road extending d accepted and used as a common corner with
I accepted the four	nd $1/2^n$ Iron Rod in a Monument Box as the best evidence of the	original corner position.
Field Measurements	see back side of LCRC	STANGE OF MICHELLER
N49°W 57.15' Set PK N69°E 167.47' Set PK S42°E 71.84' Set PK	tfor corner and accessories established to perpetuate locating the posd 1/2" Iron Rod with a 1/2" x 24" Iron Rod w/2" diameter brass ent Box & Remon Washer SW face Power Pole & Remon Washer SW face Power Pole & Remon Washer SW face Light Pole & Remon Washer SE face 12" Poplar	cap stamped sapeer county New Young M-PROFESSIONAL SURVEYOR 17623 Coveyors as the best available evidence of the county New York (New York) New Y
	s accepted by me and is generally accepted by Professional Sur	eveyors as the best available evidence of th
L/ Xu	A A	9-30-97
Signed by	Date	<u> </u>

FIELD MEASUREMENTS BETWEEN

M-3 to $\lambda-3$

GLO = 80 links South 52.80 Ft. Common Corner

M-3 to M-2

GLO = 40 chains or 2640.00 Ft. GROUND-MEA = 2681.93 Ft.

M-3 to M-4

GLO = 40 chains or 2640.00 Ft. Survey recorded in Liber 006, page 972 (7/18/85) = 2614.50 Ft. GROUND-NEA = 2613.58 Ft.

M-3 to L-3

GLO = 39.83 chains or 2628.78 Ft

PEER GROUP
APPROVED LAND CORNER
PA 3 5 0 5 1090
PA COUNTY
AV DAMS P 9. 00. SURVEYOR
AFE 9-29-97