SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

Fo	r corners in	i iiiig ricquien	ient of Act 74, Mich. P.	•	
_	Lapeer	Located In: Hadley	Corner Code ##	94 NOV 30 AM 8: 29	
		Twp.		LIBER NO. 05 A 3E NO. / 2	2
1.	Public Land Survey	т <u>6N</u> в 9E т я	M-9	Heliose I a bough	
		T R		REGISTER OF CREOS Lapeer County, Michigan	
2.	Property Controlling	S T R S T R		,	
,	in Section Miscellaneous				
J.	Property in Sec.	\$ T		Register of Deeds Stamp & File Number	×
4.	Lot No.	Recorded Plat			
5.	Private Claims				L
				2 6 5 4 3 2 2	<u> </u>
_				4 7 8 8 10 10	
i. I	Juston K. Kennedy	7, in a field survey on	une 15 19 94	5	\dashv
in li	nes 1 and 2 above were i	in conformance with regulations and ru	iles therefore as required in	the 1718161-15141	-i
Mar	agement or by a decree of	ructions of the United States Departmen a Court of Law and/or that the corner po	ints mentioned in lines 3, 4 ar	nd5 8 12 21 22 23	_
300	ve were in conformance wi	ith the rules of the Michigan Board of La re-established, monumented, re-moni	nd Surveyors or by a Decree	eota	
exp	ressed below:			10 30 29 28 27 26	ا اع–
10.	TE: Not more than 4 c on this certificate.	corners, all in the same town and ra	ange, may be recorded	13	\dashv
	on this ser integral.	,		13 32 33 34 35	3e
	•	monument and accessories and/or Set Post; 26" White Oak S35*W 34 L	•		
2	.) 1987-Kennedy, P.S. #	17623; LCRC L.002, Pg.489 - Fnd 1/2 17623; LCRC L.004, Pg.125 - Fnd 1/2 17623; Unrecorded Survey - Fnd 1/2	2" Iron	PEER GROUP APPROVED LAND CORNER BY 345 OF 1990 APPER COUNTY	
				RAY PAVIS P.S. CO. SURVEYO)FI
3.	Description of corner e	vidence found and/or method appli	ed in restoring or reestab	DATE///-29-94	_
	994 Kennedy Surveying, East & West, Which : has a gravel surface	Inc Kennedy, P.S. #17623 - Fnd is a grayel surface, and 1.10' West	1/2" Iron Rod 1' deep in of the centerline of Ba	the centerline of Brocker Road extending to Idwin Road extending to the North & South, w ch is the Northwest corner of Section 30 & t	hic
	Witnesses from LCRC	#1 & 2 were used to recover and ve	erify the location of the	e found 1/2" Iron Rod.	
	I accepted the found	d 1/2" Iron Rod as the best evidence	ce of the original corner	e position.	
E	escription of monumer	nt for corner and accessories estab	lished to perpetuate loca	ating the position of the corner:	
9 _I H-		' Iron Rod with a 1/2" x 24" Iron R	od w/2" diameter brass ca	ap stamped Lapeer County Remonumentation #17	623.
S4	4 E 59.20' Set PK & Ren	mon. Washer NE face 26" Oak			
N5		on. Washer NW face 39" Oak		THE OF MICHOLA	
N4	1 E 76.68' Set PK & Rem	mon. Washer NW face 9" Elm		THE OF BICH OF	
Th po	e selected location is sition of the original	accepted by $\boldsymbol{n}\boldsymbol{e}$ and is generally accorner.	ccepted by Professional S	Surveyors as the bast andidates willende of K.HONEDY	i i
	\bigcap 1	,		E CONFINAL I	₹

LIBER 0005 PAGE 0132