

APR 2 9 1998

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 RECEIVED FOR RECORD For corners in Located In: Metamora Corner Code # Lapeer (County) 95 AUG -4 AM 11: 17 Two. LIBER NO COSPAGE NO 23 1. Public Land Survey T _6N_ R _10E Melisse Da Vougl, REGISTER OF DEEDS ____ R ____ _ R _ LAPEER COUNTY, MICHIGAN ____ R ____ 2. Property Controlling S ____ T ___ R _ in Section _T __ 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section S __ , Recorded Plat__ 5. Private Claims __ Huston K. Kennedy in a field survey on March 28 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: A. PEER GROUP 1817-GLO Wampler, D.S.; Set Post; 12" White Oak N65°E 104 Links; 6" Black Oak S27°W 84 Links APPROVED LAND CORNER 1.) 1975-Elrich, PS #18986; Survey L.003, Pg.110 - Fnd 1/2" Iron Rod 2.) 1989-Elrich, PS #18986; Survey L.008, Pg.182 - Fnd 1/2" Iron Rod 3.) 1990-Elrich, PS #18986; Survey L.008, Pg.640 - Fnd 1/2" Iron Rod, used same wit as 1989 Survey. PA 345 OF 1990 LAPEER COUNTY 4.) 1994-Elrich, PS #18986; Survey L.010, Pg. 380 - Fnd 1/2" Iron Rod, used same wit as 1989 Survey Lung RAY DAVIS P.S. CO. SURVEYOR DATEAPPROVED 7-1395 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1995-Kennedy Survey, Inc. - Kennedy, P.S. #17623 - Fnd 1/2" Iron Rod 5" deep and in the centerline of Davison Lake Road extending to the East & West, which has a gravel surface and 12 feet West of the centerline of Barber Road extending to the North & South, which has a gravel surface. The corner common to Sections 1 & 2, T5W, R10E, Oxford Twp. (K-1) is located 83.28 feet to the East. Witnesses from Survey #1 & 2 were used to recover and verify the location of the found 1/2" Iron Rod. I accepted the found 1/2" Iron Rod as the best evidence of the original corner position. FIELD MEASUREMENTS BETWEEN K-13 to L-13 2654.78 Ft., GLO = 40 chains or 2640.00 Ft. K-13 to J-13 2649.10 Ft., GLO = 40 chains or 2640.00 Ft. K-13 to K-1 82.28 Ft., GLO 10 links or 6.60 Ft. Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-13 I replaced the found 1/2" Iron Rod with a 1/2" x 24" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation, PS #17623 K-13 S11°E 26.29' Set Nail & Remon. Washer West face 12" Cherry S16°W 24.83' Set Nail & Remon. Washer NW face 10" Oak S47°E 42.33′ Set Nail & Remon. Washer NE face 26" Oak N52°W 49.98' Set Nail & Remon. Washer SW face 17" Cherry East 83.28 feet corner common to Sections 1 & 2, T5N, R10E, Oxford Twp. (K-1) The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available endeance of position of the original corner.

17623

Surveyor's Michigan License No.

__ Date __

FORM APPROVED BY MICHIGAN STATE BOARD OF PR

REVISED MAY AN 1815