SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

REMONITHENTATION

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE

98 FEB 18 PM 2:50

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in

Located In: MetamoraCorner Code # Lapeer Township (County) T6N R10E 1. Public Land Survey M-42. Property Controlling in Section 3. Miscellaneous Property in Sec.

Maliesa Da	Vaugh
REDISTER OF	PPEOS.

Register of Deeds Stamp & File Number

. Lot No	_, Recorded Plat	
i. Private Claims _		
		· ·

1, Huston K. Kenned Ya field survey on 08/15, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	<u> </u>	В	C I	D	E I	F 0	5 }	i	Į.	3 K	C 1	M
					1							
2		6	-	5	-	4	:	3	:	2 {		<u> </u>
3	├—	-	┼┈	╁	├	-	 					
4		ļ	-	8	-	 9 1	1	0	1	1	1	2
5		-	 	┼	-		-					
6	1	 		<u> </u>	- 1	6	1	 5	1	4	1]]
7		<u> </u>		 	 			<u> </u>				
8	1	9	:	20 <u>—</u>	1-2	1	2	 	2	3	2	4
9	_	<u> </u>	-	-	ļ							
10	-3	ļ }	-:	ا ـــود	<u> </u>	8—	_2	7	2	6	2	5
11		-		-	ļ							
12	_3) 1	-3	2-	-3	3	3	4	3	5	<u> </u>	6—
13	L	<u> </u>	L	<u> </u>	<u> </u>	<u> </u>						

- Description of original monument and accessories and/or subsequent restoration:
 - 1817-GLO Wampler, D.S., Set Post 23" Birch N40°W 40 Links
 - 1.) 1989-Tietsema, PS #20712; Unrecorded Survey Fnd 1/2" Iron Rod
 - 2.) 1989-Carlson, PS #9189; Unrecorded Survey Fnd 1/2" Re-rod
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1997 Kennedy Surveying, Inc. Kennedy, PS #17623 Fnd 1/2" Iron Rod .70 feet below the surface, 3.00 feet West of the existing centerline of Thornville Road extending to the North & South, which has a gravel surface. The West 1/4 corner of Section 7, T6N, R11E, Dryden Township (A-4) is located 154.18 feet to the North.

Witnesses from unrecorded Surveys #1 & 2 were used to recover and verify the location of the found 1/2" Iron Rod.

I accepted the found $1/2^n$ Iron Rod as the best evidence of the original corner position.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H-4 I replaced the found 1/2" Iron Rod with a 1/2" x 24" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation H-4 N51 W 33.09' Set PK & Remon Washer NW face 24" Oak

S89 E 36.34' Set PK & Remon Washer South face 16" Elm

S26 E 63.84' Set PK & Remon Washer South face 9" Poplar

N34'W 31.80' Set PK & Remon Washer NE face 10' Walnut

North 154.18 feet West 1/4 corner of Section 7, T6N, R11E, Dryden Township (A-4)

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the TE OF MICHIGA position of the original corner.

Surveyor's Michignan License No.

CPESSIONAL DRIS, JA

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYOR'S, JAN. 28, 1971 REVISED MAY 14, 1975

HUSTON EVINED

SURVEY & REMONUMENTATION

MAR 1 3 1998

LIBER 0 0 0 6 PAGE 0 0 1 6

SECTION

PIELD MEASUREMENTS BETWEEN

M-4 to A-3

No GLO GROUND-MEA = 154.18 Ft.

H-4 to A-4

No GLO GROUND-MEA = 154.18 Ft.

H-4 to H-3

GLO = 40 chains or 2640.00 Ft. Unrecorded Survey by McAlpine, PS #1015 (May 1950) = 2716.55 Ft. GROUND-MEA = 2715.79 Ft.

H-4 to H-5

GLO = 40 chains or 2640.00 Ft. Unrecorded Survey by McAlpine, PS #1015 (May 1950) = 2426.72 Ft. GROUND-MEA = 2421.72 Ft.

PEER GROUP

Jay 7-29-97