

SURVEY &
REMONUMENTATION

1993

COMMISSION

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

93 DEC 22 PM 2:40

LIBER 5 PAGE 5

Shelby W. Money
REGISTERED PROFESSIONAL
LAPPEER COUNTY SURVEYOR

For corners in

LAPPEER
(County)

Located In: Dryden Township Corner Code #

- | | | |
|---------------------------------------|--------------------------|-------------|
| 1. Public Land Survey | T <u>6N</u> R <u>11E</u> | <u>M-11</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims _____ | | |

Register of Deeds Stamp & File Number

I, Shelby W. Money, in a field survey on September 13, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

POST G.L.O. NOTES / PAGE 347

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SET USING SURVEY BY KINGS / KOB DATED AUGUST 21, 1987

NO OCCUPATION TO THE WEST

SET LAPPEER REMONUMENTATION CORNER 96.74' NORTH OF A-11 ALMONT TOWNSHIP ON LINE FROM WEST 1/4 POST OF SECTION 36

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 1/2" REBAR WITH BRASS LAPPEER COUNTY REMONUMENTATION CAP MARKED #30092 / M-11

- | | | |
|---------|--------|---|
| AZ 230• | 86.65' | NAIL WITH LAPPEER COUNTY TAG IN SOUTHEAST FACE OF 30" HICKORY |
| AZ 205• | 57.58' | NAIL WITH LAPPEER COUNTY TAG IN SOUTHEAST FACE OF UTILITY POLE |
| AZ 350• | 97.03' | NAIL WITH LAPPEER COUNTY TAG IN SOUTHWEST FACE OF UTILITY POLE |
| AZ 45• | 45.82' | NAIL WITH LAPPEER COUNTY TAG IN NORTHWEST FACE OF TWIN 15" LOCUST |
| AZ 150• | 68.06' | NAIL WITH LAPPEER COUNTY TAG IN SOUTHWEST FACE OF TRIPLE ELM |



Signed by *Shelby W. Money* Date December 21, 1993
Surveyor's Michigan License No. 30092