SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Lapeer Located In: Corner Code # Almont Township 1. Public Land Survey T6N R12E H-2 T R T R T R T R T R T R T R T R T R T	94 DEC 29 ANTO: 16 IDER NO. C5 ANTO: NO. 191 ANTO: NO. C
TR R TR	REGISTER GT TEUS LAPER GT TEUS
2. Property Controlling S_T_R	Register of Deeds Stamp & File Number B C D S F G H I J K L 1 6 - 5 - 4 - 2 - 2 - 7 - 8 - 9 - 10 - 11 - 12 - 18 - 27 - 16 - 15 - 14 - 13 - 19 - 19 - 20 - 21 - 22 - 23 - 24
1. Shelty W. Money in a field survey on 11-14 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 122 133 1. Joseph Wampler, D.S. in 1817 pages 556 - 560 set post. No witnesses left. 2. Gilbert Bates 1865 pages 82 - 83 Stone 16" - 10" - 7". 3. Unrecorded survey by Walter Lehner, P.S. 123 on 3-26-51 as an unknown. 4. Survey recorded by Robert Kay, P.S. 14096 on 7-20-78 in liber 4, page 745, of surveys as 5. Survey recorded by Harold Elrich, P.S. 18986 on 10-23-79 in liber 5, page 545, of surveys 0.7" South and 1.5' East). 6. Survey recorded by Earel Gravlin, P.S. 23510 on 3-31-81 in liber 6, page 66, of surveys 7. Unrecorded survey by Charles Getz, P.S. 25843 on 11-17-82 as a found 3/8" iron. 6. Survey recorded by Harold Elrich, P.S. 18986 on 7-9-873 in liber 7, page 610, of surveys 8. Survey recorded by Harold Elrich, P.S. 18986 on 7-9-873 in liber 7, page 610, of surveys 9. Survey recorded by Harold Elrich, P.S. 18986 on 7-9-873 in liber 7, page 610, of surveys 9. Survey recorded by Earl Gravlin, P.S. 23510 on 4-24-92 in liber 9, page 711, of surveys 9. Survey recorded by Earl Gravlin, P.S. 23510 on 4-24-92 in liber 9, page 711, of surveys 10 Unrecorded survey by Ray Davis, P.S. 22430 on 2-27-94 as a found 1/2" rebar.	18 17 16 15 14 13 19 20 21 22 23 74
under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of 6 for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-emonumented, recovered, found as expressed below: NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1. Joseph Wampler, D.S. in 1817 pages 556 - 560 set post. No witnesses left. 2. Gilbert Bates 1865 pages 82 - 83 Stone 16" - 10" - 7". 3. Unrecorded survey by Watter Lehner, P.S. 123 on 3-26-51 as an unknown. 4. Survey recorded by Robert Kay, P.S. 14096 on 7-20-78 in liber 4, page 745, of surveys a 5. Survey recorded by Harold Elrich, P.S. 18986 on 10-23-79 in liber 5, page 545, of surveys 27. Unrecorded survey by Charles Getz, P.S. 25510 on 3-31-81 in liber 6, page 66, of surveys 28. Survey recorded by Earel Gravlin, P.S. 23510 on 12-13-78 in liber 5, page 102, of surveys 39. Survey recorded by Eard Gravlin, P.S. 23510 on 4-24-92 in liber 5, page 610, of surveys 39. Survey recorded by Eard Gravlin, P.S. 23510 on 4-24-92 in liber 7, page 611, of surveys 39. Survey recorded by Eard Gravlin, P.S. 23510 on 4-24-92 in liber 9, page 711, of surveys 39. Survey recorded by Eard Gravlin, P.S. 23510 on 4-24-92 in liber 9, page 711, of surveys 39. Survey recorded survey by Ray Davis, P.S. 22430 on 2-27-94 as a found 1/2" rebar.	18 17 16 15 14 13 19 20 21 22 23 74
on this certificate. 10 A. Description of original monument and accessories and/or subsequent restoration: 11 12 13 13 14 15 16 17 17 17 18 18 19 19 19 19 19 19 19 19	30 29 28 27 26 25
1. Joseph Wampler, D.S. in 1817 pages 556 - 560 set post. No witnesses left. 2. Gilbert Bates 1865 pages 82 - 83 Stone 16" - 10" - 7". 3. Unrecorded survey by Walter Lehner, P.S. 123 on 3-26-51 as an unknown. 4. Survey recorded by Robert Kay, P.S. 14096 on 7-20-78 in liber 4, page 745, of surveys at Survey recorded by Harold Elrich, P.S. 18986 on 10-23-79 in liber 5, page 545, of surveys 0.7' South and 1.5' East). 6. Survey recorded by Earle Gravlin, P.S. 23510 on 3-31-81 in liber 6, page 66, of surveys at Unrecorded survey by Charles Getz, P.S. 25843 on 11-17-82 as a found 3/8" iron. 6. Survey recorded by Earl Gravlin P.S. 23510 on 12-13-78 in liber 5, page 102, of surveys at Survey recorded by Harold Elrich, P.S. 18986 on 7-9-873 in liber 7, page 610, of surveys 9. Survey recorded by Earl Gravlin, P.S. 23510 on 4-24-92 in liber 9, page 711, of surveys at 10 Unrecorded survey by Ray Davis, P.S. 22430 on 2-27-94 as a found 1/2" rebar.	
 Joseph Wampler, D.S. in 1817 pages 556 - 560 set post. No witnesses left. Gilbert Bates 1865 pages 82 - 83 Stone 16" - 10" - 7". Unrecorded survey by Walter Lehner, P.S. 123 on 3-26-51 as an unknown. Survey recorded by Robert Kay, P.S. 14096 on 7-20-78 in liber 4, page 745, of surveys a Survey recorded by Harold Elrich, P.S. 18986 on 10-23-79 in liber 5, page 545, of survey 0.7' South and 1.5' East). Survey recorded by Earel Gravlin, P.S. 23510 on 3-31-81 in liber 6, page 66, of surveys a Unrecorded survey by Charles Getz, P.S. 25843 on 11-17-82 as a found 3/8" iron. Survey recorded by Earl Gravlin P.S. 23510 on 12-13-78 in liber 5, page 102, of surveys a Survey recorded by Harold Elrich, P.S. 18986 on 7-9-873 in liber 7, page 610, of surveys 9. Survey recorded by Earl Gravlin, P.S. 23510 on 4-24-92 in liber 9, page 711, of surveys a 10 Unrecorded survey by Ray Davis, P.S. 22430 on 2-27-94 as a found 1/2" rebar. 	31 32 34 35 36
	s as 3/8" iron. (Also found a 1/2" iron s a found 3/8" iron. a found 1/2" iron bar. s a found 1/2" iron bar.
Found a 5/8" rebar and a 3/8" rebar in the gravel road (Farley Road), the easterly 5/8" rebar including the 1951 survey by Lehner. Fence line to the East and West. 3/8" fron is 0.6' North irons measure 1.40 feet between them.	appears to match the most history and 1.3' West of 5/8" iron. The two
Witnesses: from item 10 above Distances: East to I-2 2675.5 N 20° W 43.91' Rivet in North end 12" drive culvert S 20° W 62.13' PK nail in 9" tree North to H-2 3001.6 East 37.12' Spike in 8" Tree. South to H-3 2636. West 34.45' Found capped iron East 33.05' Found iron Found 1/2" bar 0.60' North and 1.33' West. C. Description of monument for corner and accessories established to perpetuate locating	9' (Bates 2874.96') 5' (Bates 2979.90')
Removed 5/8" rebar and replaced with a 1/2" by 18" rebar an placed a standard Lapeer Cour "H - 2 30092" at same location Az 90° 37.12' Found PK, set nail with Lapeer County tag in South face of 8" Hickory. Az 200° 62.10' Found PK, set nail with Lapeer County tag in East face 12" Poplar. Az 330° 43.89 Found rivet at the North end of a 12" CMP culvert. Az 350° 143.35' Set nail with Lapeer County tag in East face 26" Oak Set Nail With Lapeer County tag in	the position of the corner:
West 34.50' Found 1/2" iron with cap # 23510. Signed by Surveyor's Michigan License No. 30092 PROFESSIONAL PROFESSIONAL	

##10005 MSE0191