SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

***			DATION CERTIFIC Act 74, Mich. P.A. 1		
For corners in				RECEIVED FOR RECORD	
Lapeer (County)	Located In: Alm	Located In: Comer Code # Almont Township		91, DEC 29 AITIO: 21	
1. Public Land Survey	Land Survey T 6N R 12E J-1 T R T R T R			LISER NO. 05 1. C. NO. 195 Maria Electronia NECUSTER OF DEEDS	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR			LATESH COUNTY HOUSE	GAN ,
4. Lot No , Reco 5. Private Claims	rded Plat			A B C D & F G H	I J K L
I, Sheby W. Money under requirements of P.A. 74, N in conformance with regulations the United States Department of for that the corner points mentiful Michigan Board of Land Surveyor re-monumented, recovered, found	lichigan P.A. of 1970, the com and rules therefore as required the Interior, Bureau of Land Ma oned in lines 3, 4 and 5 abo is or by a Decree of a Court of	er points mentioned in li I in the current manual o inagement or by a decre ve were in conformanc	nes 1 and 2 above were if survey instructions of e of a Court of Law and e with the rules of the	3	14 13
NOTE: Not more that 4 cor on this certificate.	mers, all in the same tov	m and range, may i	pe recorded	9 29 28 27-	26 25
A. Description of original mo	nument and accessories a	nd/or subsequent re	storation:	12 31 32 33 34	35 36
1. Joseph Wampler, D.S	. in 1817 pages 556 -	560 set post. No v	vitnesses left.		
2. Gilbert Bates in 1854	pages 80 - 81 Stone	15" - 13" - 10"			
3. Unrecorded survey by	Chales Getz, P.S. 2584	3 on 11 -17 -82 as	a found iron.		
B. Description of corner e	evidence found and/or r	nethod applied in re	estoring or reestabl	lishing corner:	
Found a 1/2" rebar in a fen	ce running East and W	est on the North sid	le of a drain. Tree	line to the South.	
S 20° E 23	3.33 Nail 10" Elm 1 3.22' Nail 6" Elm 2.25' Nail 10" Elm	West to West to		ship) 345.60° ship) 2274.48 ship) 2732.07 (Bates 2732.16 ship) 2735.30° (Bates 2723.1	
C. Description of monume	ent for corner and acces	sories established	to perpetuate locat	ting the position of the corner:	
Placed standard Lapeer Co	ounty Remonumentation	ı cap stamped " J -	1 30092" on four	nd iron.	
Az 180° 2.73' Se Az 180° 25.30' No Az 255° 70.05' Se	et PK with Lapeer Count of PK with Lapeer Count of the end 36" CMP culve of PK with Lapeer Count of PK with Lapeer Count	y tag in East face o t at ditch	f multiple 6" Elm.		
Signed by Surveyor's Michigan License	No. 30092	Da	te <u> 2 22 94</u>		
Sarroyor O Mioniggy, 2001.5	<u> </u>	SHELBY W.	Can	PEER GROUP	/EYORS, JAN. 28, 197 REVISED MAY 14,197 REVISED JAN., 196
		MONEY PROFESSION SURVEYOR No. 30092	~	PA 345 OF 1990 LAPSER COUNTY	

RAY DAVIS P.S. CO. SURVEYOR DATE 12.28.91