

## MAR 2 9 1999

## REMONUMENTATION

SECTION

_			Requirement of Act 74,		'ስ	CEIVED FOR	DECUBL	
For	corners in				• • • •			
_ <u>L</u>	(County)	Located in: Elba Township	Corner Code #		98	OCT 27 AM	10: 53	
1. 8	Public Land Survey	<u>T7N</u> R <u>9E</u> T R T R T R	<u>F-13</u>		L.F	Maliosa Da V REGISTER OF C APEER COLUMN	augh EEOS EEBIGAH	
i 3. I	Property Controlling in Section Miscellaneous Property in Sec.	T R T R S T R S T R S T R S T R			399 Registe	of Deeds Sta	mp & File Number	
<b>4</b> . i	4. Lot No, Recorded Plat							
i, h	fuston K. Kennedy , ir irrements of P.A. 74, Michigan Promance with regulations and ruled States Department of the Interthe corner points mentioned in lir	n a field survey on <u>July 1</u> 2.A. of 1970, the corner points es therefore as required in the rior, Bureau of Land Managen nes 3, 4 and 5 above were in c	4, 19 <u>98</u> do hereby st s mentioned in tines 1 and 2 current manual of survey ins nent or by a decree of a Cour conformance with the rules	ate that under above were in structions of the t of Law and/or of the Michigan	1	D E F G H 5-4-3 8-9-10 17-16-15	1 J K L M	
	rd of Land Surveyors or by a wered, found as expressed below		established, re-established,	, incrumented,	8 19	20 21 22	23 24	
NO	TE: Not more than 2 corner on this certificate.	's, all in the same town an	d range, may be recorded		9 10 30 11 12 31	29 28 27	26 25	
A. Description of original monument and accessories and/or subsequent restoration:  1822-GLO Wampler, D.S.; Set Post 18" Birch N56°E 11 Links; 8" Ironwood S65°W 28 Links 1.) 1973-Mitchell, PS #6936; LCRC L.2, pgs.115 & 116 – Fnd a PK Nail 2.) 1977-Elrich, PS #18986; LCRC L.3, pg.08 – Fnd a PK Nail 3.) 1977-Elrich, PS #18986; Survey L.4, pg.259 – Fnd a PK Nail, used same wit as 1977 LCRC 4.) 1988-Elrich, PS #18986; Survey L.7, pg.379 – Fnd a PK Nail 5.) 1991-Bates, PS #16699; Survey L.8, pg.498- Fnd a PK Nail 6.) 1997-Elrich, PS #18986; Survey L.12, pg.177 – Fnd a PK Nail							LAND CORNE 15 OF 1990 ER COUNTY S. CO. SURVEY	
В.	7.) 1998-Gravlin, PS #23510; Survey L.12, pg.778 – Fnd a Monument Box  DATE  OATE  OATE  OATE  OATE  OATE  OATE  OATE  North // Corner of Section 4, T6N, R9E, Hadley Twp. (F-1) is located 334.21 feet to the West.							
	Witnesses from Survey #4, 5, 6 & 7 were used to recover and verify the location of the found $\frac{1}{2}$ " Iron Rod in a Monument Box.							
	l accepted the found ½" Iron Rod in a Monument Box as the best evidence of the original comer positon.							
	Field measurements se	e back side of LCRC						
C.	Description of monument of F-13 I replaced the found the existing Monument of N41°W 151.74' SE commod S41°E 44.53' Set Mag N507°W 140.27' Set Mag N57°W 47.38' Set Mag Nest 334.21 feet, North	nd 1/2" Iron Rod with a Box Ier of house #2988 Vail & Remon Washer i I Nail & Remon Washer Nail & Remon Washer	1/2" x 24" Iron Rod w/2 NE face 9" Box Elder er East face Power Po NW face 9" Poplar	?" brass cap s le	tamped Lape	er County Ray	DN DY IONAL	
The	e selected location is acceptain position of the original of	cepted by me and is gorner.	enerally accepted by			A ROFESSIO	able to dence of	
Sig	ned by: Qualor 1	4. Kanad	<del></del>	Date 9	-11-98		3111	
Sur	veyor's Michignan License	No	7.3					