1993

COMMISSION

For corners in

## REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

$\nabla \Gamma \nabla \Gamma$	11/F D	700	nr	00	ni
RECE	1751	Jan 1 1 5 /	14.5	1 1	Νi
412 (-)		1 1771	1 - 1	5.31	1

93 DEC 22 014 2 53

29 NEP 77	10 T. 30
UBER to 5	114 to 22
Milison	11/25
2.2011.001 (	

	LAPEER	Located In:	Corner Code ##			1052				io a u	
	(County)					3 85.				,,,,	
1.	Public Land Survey	т <u> 7N</u>	<u>M-11</u>								
	•	T R									
		T R									
								. ~	٠.		
2.	Property Controlling			,				**,			
	in Section						-,	•	1		
3.	Miscellaneous			Register	of O	eeds S	Яатр	& Fit	e Nun	nber	
	Property in Sec.	S T R				•	-	<del>;</del>			
					, '		$\rightarrow f$		(		
		Recorded Plat		<u> </u>	В,	C D,	E F.	G H	i J	К	L N
5.	Private Claims				  -6	, + 5	<u> </u>	-3		<u>.</u>	-
				3	Ĭ	Ĭ,	<u>Li'</u>		لــــــــــــــــــــــــــــــــــــــ		
				4	Ţ					1	12
	אנים או דו פד	CH in a field survey onNO	VEMBER 19 93	5	- [	T i		Ti	Τ'n		[
ı,	hereby certify that under r	requirements of P.A. 74, Michigan P.A.	of 1970, the corner points mentione	d					$\neg \neg$		_
in l	lines 1 and 2 above were	in conformance with regulations an	id rules therefore as required in th	e [	-18 	<del>-</del> -17— │	16-	<del></del> 15-	<del>   </del> 'i	4	-13 
Cui	rrent manual of survey ins	tructions of the United States Depart	tment of the Interior, Bureau of Lan	d (-	+		<del>  -   -</del>	1		$\top$	+
Ma	nagement or by a decree o	of a Court of Law and/or that the corne with the rules of the Michigan Board (	or points mentioned in lines 3, 4 and	a	-19	-20-	21	22-	<del>2</del>	3—	-24
Co	urt of Law: established.	re-established, monumented, re-r	monumented, recovered, found a	s 9 –	+		++-	++	+		+
	pressed below:	, , , , , , , , , , , , , , , , , , , ,		10	-30	29	-28-	27-	2	5——	-25
NC	OTE: Not more than 4	corners, all in the same town ar	nd range, may be recorded	11	+	<b></b>	<del></del>	++	$\dashv$	+	+
	on this certificat			12	-31	32	<u>3</u>	34-	3	5	-36
				13	لــــــــــــــــــــــــــــــــــــــ		<u> </u>	$\perp \perp$	$\perp \perp \perp$	$\perp \!\!\! \perp$	
A.	Description of origina	al monument and accessories and	d/or subsequent restoration:								
		SURVEY BY JOS. WAMPLER									
	IRONWOOD 1	O" NORTH 4 1/2º WEST 52	2 LINKS & BEECH 11" SO	UTH 86°	WES.	T 35	LINH	(S			
											_

1973 LAND CORNER RECORDATION CERTIFICATE LIBER 002, PAGE 439, FOUND 1/2" IRON, SOUTH 64.83 FEET TO A-11, T7N-R11E BUCKERFIELD P.S. #10868
1973 RECORDED SURVEY LIBER 002, PAGES 555-558 FOUND 1/2" IRON ROD ELRICH P.S. #18986

1973 LAND CORNER RECORDATION CERTIFICATE LIBER 002, PAGE 499 FOUND PIPE SAME THREE WITNESSES AS 1983 SURVEY ELRICH P.S. #18986

1989 RECORDED SURVEY LIBER 008, PAGE 727 FOUND 3/4" IRON

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 NOV ELRICH P.S. #18986 FOUND 1/2" PIPE, FOUND TIE SOUTH TO A-11, T7N-R11E, TO BE SAME AS 1973 LAND CORNER RECORDATION CERTIFICATE LIBER 002, PAGE 439 & LAND CORNER RECORDATION CERTIFICATE LIBER 002, PAGE 707, AT INTERSECTION OF HUNTERS CREEK ROAD ON WEST AND CENTERLINE OF FIVE LAKES ROAD

A-11, T7N-R11E, NORTH 64.82 FEET TO M-11, T7N-R10E, SWARTZ P.S. #16945

ACCEPTED FOUND 1/2" PIPE AS BEST EVIDENCE OF ORIGINAL POSITION OF THE NORTHEAST CORNER OF SECTION 36

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## M-11 1/2" PIPE WITH REMONUMENTATION CAP

SOUTH 85° EAST 155.79 FEET SET NAIL & REMONUMENTATION TAG IN TRIPLE ELM, 6", 3" & 3"

SET NAIL & REMONUMENTATION TAG IN 24" MAPLE SOUTH 15° EAST 111.99 FEET

SET NAIL & REMONUMENTATION TAG IN 14" MAPLE SOUTH 50° WEST 76.84 FEET

NORTH 20° WEST 134.20 FEET SET NAIL & REMONUMENTATION TAG IN POWER POLE

SOUTH 15.48 FEET FOUND 1/2" PIPE AT INTERESECTION OF CENTERLINE/CENTERLINE HUNTERS CREEK & FIVE LAKES ROADS

SOUTH 64.87 FEET FOUND 1/2" PIPE AT A-11, T7N-R11E Harred N. El

N. ELRICH

POFFSSI

HAROLD

\*

OF MICH

FORM APPROVED BY MICHIGAN STATE BOARD PAND SUF

18986 Surveyor's Michigan License No. 118FR 1005 FATTE 22