## SURVEY & REMONUMENTATION

APR 2.8 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

	RECEIVED
LAPEERLocated in: Corner Code #  (County) ATTICA TOWNSHIP	94 DEC -9 PH 3: 10
1. Public Land Survey T 7N R 11E M-9	LIBER HO. 65 I MGE NO. 124
TR TR	Helissa De Vaugh
T R	REGISTER OF DEFOS LAPEER COCHET TOHIGAN
2. Property Controlling S T R	<u> </u>
3. Miscellaneous S T R	
Property in Sec. S TR	Register of Deeds Stamp & File Number
	•
4. Lot No, Recorded Plat	ABCDE'FG-HIJKL
	2 - 6 - 5 - 4 - 3 - 2 - 1 -
	3 + + + + + + + + + + + + + + + + + + +
I, SHELBYW MONEY in a field survey on SEPTEMBER 2 , 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentic	oned in 5
lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current of survey instructions of the United States Department of the Interior. Bureau of Land Management of	manual or by a 6 18 17 16 15 14 13
decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above we conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of	were in
established, re-established, monumented, re-monumented, recovered, found as expressed below:	8 -19 - 20 - 21 - 22 - 23 - 28 -
NOTE: Not more that 4 corners, all in the same town and range, may be recorded	10 30 29 28 27 26 25
on this certificate.	10 29 23 27 20 13
	12 31 32 33 34 35 36
	. 13
A. Description of original monument and accessories and/or subsequent restoration:  G.L.O. 1822 PAGE 378 JOSEPH WAMPLER WITNESS 1919 UNRECORDED LAPEER COUNTY ROAD COMMISSI PLAN FOR NEWARK ROAD / COUNTY LCRC 1973 LIBER 003 PAGE 273 DOUGLAS W. HOOTH, #7966	SET POST, NO WITNESSES FOUND TY ROAD #58 FOUND, SET, 5/8" ROD WITH MDSH DISC IN MONUMENT BOX
B. Description of corner evidence found and/or method applied in restoring or reestablish	ing corner: OF MICH.
	A A STATE OF THE S
FOUND, 5/8" REBAR WITH 11/2" MDSH CAP IN A MONUMENT BOX CENTERLINE OF AN ASPHALT ROAD TO THE WEST	SHELBY W.
THIS CORNER VERIFIED BY:	PROFESSIONAL N
LCRC WITNESS 1977 UNRECORDED S 15° E 76.55' FOUND, MDSH TAG ON A 21" MAPLE	Ma No Sh
M-9 TO M-8, T.7N., R.11E. G.L.O. 40 CHAINS MEASURE 2665.00	
M-9 TO M-10, T.7N., R.11E. G.L.O. 40 CHAINS MEASURE 2658.12	ESSION ESSION
C. Description of monument for corner and accessories established to perpetuate locating to	the position of the corner:
FOUND, 5/8" ROD WITH 11/2" MDSH DISC IN A MONUMENT BOX. LEFT IN	
AZIMUTH 95° 180.87' FOUND, PK'NAIL "AND" SET NAIL WITH I	ACE OF A UTILITY POLE
AZIMUTH 150° 76.46' FOUND, DOUBLE HEADED NAIL WMDSH AZIMUTH 355° 144.30' FOUND, DOUBLE HEADED NAIL WMDSH AZIMUTH 00° 30.90' FOUND, IRON W/BRASS CAP IN MONUME	I TAG IN THE SOUTHWEST FACE OF A 20" OAK I TAG IN THE EAST FACE OF A UTILITY POLE
	PEER GROUP APPROVED LAND CORNE
	APPROVED LAND CORNE