Signed by Michael

Surveyor's Michigan License No.

fill the land 1600.	R	REMONUMENTATION	•			
	LAND CORNE	R RECORDATION CERTIF	ICATE	, the second second		Transport of the second
	Filing Requir	ement of Act 74, Mich. P.A.	1970 - R	F <b>C</b> FIVED s	nn ne	0000
For corners in		SEVE	- s2-	9 JAN -6		
LAPEER	Located In:	Commission				
`(County)	OREGON TWP.	Corner Códe #		Melissa D REGISTER OF APEER COUNTY	e Vangl F DEEDS 7. MICHIG	AN
Public Land Survey	T_8 R_9 T R T R		145)	Deeds Stamı		
Property Controlling S_ in Section S_     Miscellaneous S_ Property in Sec. S_	T R T R T R T R			- County		———
Lot No, Recorded     Private Claims	Plat		1 A B	CDEF	GН	IJĶ
5. Private Claims			2 6	5 4	3	2.
MICHAEL G. HAY	in a field survey		3 7	8 9	10	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the Management or by a decrea of the United States Department of the Interior P.				···17 ··16	15	14
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 Court of Law: established to established to the surveyors of by a Board of Land Surveyors or by a Board of Land				- 2021	22	23
		maniferated, recovered, found as	10 30	29 28	27	26
NOTE: Not more than 4 corner on this certificate.	s, all in the same town and r	ange, may be recorded	11 12 13	32 33	34	35
A. Description of original mo 1821-JOSEPH WAMPLER D.S 1864-GILBERT BATES C.S. 1974-ROBERT G. KAY P.S.  1975-ROBERT G. KAY P.S. 1975-BERNARD HENDERSON I 1976-LELAND D. BATES P.S. 1995-EARL E. GRAVLIN P.S.	STAKE ELM 22 N13E WI 14096 L3 P1 FOUND RI N8 N6 N8 14096 L3 P289 (SAME A P.S. 16043 L2 P133 (S	HITE OAK ORIGINAL E-ROD  30W 23.83' 8"TRIPLE AS 50E 33.63' 20" OAK 35E 23.10' 15" OAK AS 1974 TIES)  AME AS 1974 TIES)		10 N40E 8	ROUP	ANER 1
	N8	ND ½ IRON OW 23.72' N/S 8" ASH 5E 33.55' N/S 36" OAK		9-17	98	
1997-RAY D. DAVIS P.S. 2	N80 2430 L0011 P0971 (SAN	DE 23.07' N/S 24" OAK ME AS 1995 TIES)				
B. Description of corner evidence	found and/or method applied in	1 restoring on the state of				
18986 33' WEST OF TH RECOVERED THREE WITH K-2 TO K-1 3110.35 K-2 TO K-3 2641.26	41101 FOUND %" IRON HE WEST COR OF SECTION HESSES CLOSE IN RECOR (M) 3110.42(R-HBE) (M) 2641.27(R-HBE)	ROD IN CENTER LINE OF N I ALSO FOUND DOWNED DED DISTANCES.	FENCE L	INE TO EA	FIC #	:
C. Description of monument for cor K-2 SET STANDARD REMONUM N80W 23.79' 9" TRIPL N45E 33.63' 26" OAK N80E 23.15' 18" OAK S40W 47.06' 28" OAK	ner and accessories established ENTATION CAP ON FOUNI E ASH FND P.K. IN N F FND NAIL IN BOTTLE CA	ed to perpetuate locating the pos D %" IRON FACE AP NW FACE	sition of the	corner	MICHA G. HA ROFESCI SURVEY No. 41101	Y A

12-30-98