MAR 1 3 1998

SECTION

1997 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

97 NOV 12 PM 2:50

For corners in: OREGON	TWP.						•	
LAPEER	_ Located In:	Corner Code #		M	lissa. D	e Vaug	4	
(County)				RE	GISTER O	r ofeo:	Same	
1. Public Land Survey	T <u>08N</u> R <u>09E</u> TR	<u>M-1</u>		LAPES	, 'a			
Property Controlling S in Section S Miscellaneous S Property in Sec. S	T R T R		Register (of Deeds :	<u></u> -			<u></u>
	corded Plat		1 A 1	S C D	E F G	∍ H I	J K	L
5. Private Claims			3 4	7 8		10	11	1
de become portification under rac) , in a field surve	A. of 1970, the corner points mentioned		8 17	16	15	14	1
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			7 8 1	9 20	21	22	23	2
Court of Law; established, expressed below:	re-established, monumented,	re-monumented, recovered, found as		30 29	28	27	26	2
NOTE: Not more than 4 con this certificate	corners, all in the same tow	n and range, may be recorded	12	32	33	34	35	
1834 GLO; WAMPLER, I 1977 HENDERSON-BAT 70.18' 12" OAK, 1978 HENDERSON-BAT 1978 BATES, P.S.#1669	D.S.; SET POST; ELM 7" S ES; BATES, P.S.#16699; S45E 47.16' 10" ASH ES: BATES, P.S.#16699;	nd/or subsequent restoration: 613W 80LKS., LINDEN 13" N35E SURVEY; L.084,PG.408; SET IF SURVEY; L.004,PG.474; FND. 1 FND. 1/2" ROD; SAME WITS AS ID. 1/2" ROD	(ON N10E 1/2" ROD;	SAME W	ITS AS			
A-13 TO M-12 2615.75'	HENDERSON-BATES '77 HENDERSON-BATES '77 HENDERSON-BATES '77	•						
B. Description of corner 6	evidence found and/or method #37276; FND. 1/2" W/ ST/	d applied in restoring or reestablishin ANDARD REMON CAP	g corner:					

NOTE: THIS CORNER IS COMMON WITH A-1 T8N-R10E, M-13 T9N-R9E, AND A-13 T9N-R10E

C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner
	THE TOP WE CTANDADD DEMONICAD

M-1 1/2" ROD W/ STANDARD REMON CAP

Signed by

Surveyor's Michigan License No.

N13°E, 21.12' NAIL W/ REMON TAG IN NW FACE 10" ASH

S42°E, 47.16' NAIL W/ REMON TAG INNE FACE 8" ASH S70°W, 70.18' NAIL W/ REMON TAG IN N. FACE 16" OAK N64°E, 33.53' NAIL W/ REMON TAG IN NW FACE 16" WILLOW

N60°W, 36.60' NAIL W/ REMON TAG IN SW FACE 8" ASH

Date 11-11-97

SURVEYORS, JAN. 28, 1971

JONATHAN M. FIELD PROFESSIONAL

SURVEYOR

LIDER 0 0 0 5 PAGE 0 4 4 8

PA 345 OF 1990

PEER GROUP

PPROVED LAND CORNER

9