LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY_6_	T. 8 N. R. 10 E.	<u>C-/</u>	
2. PROPERTY CONTROLL-		<u>c-/</u>	7
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. R E.		
4. LOT NO, RECO	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on			
A. Description of original monument and accessories and/or subsequent restoration:			
24" White Jak Common to 576			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
Found T" Shaped Iron 4" Below Gravel Recovered with interess Received from Henderson Surveyores In Lapoer, Mangen			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
"T" Shaped I	- 60 71		
N.30° E. 27. S.42° W. 37. S.42 E 36. EAST 103.	32 Telephone 60 Taiple 15" 45 8" Hickor 04 15" IRON R. T. 9N. R.	SALS. SALS. N.F. CORNER CO	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN REG	STRATION NO.		(SEAL)
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	CHIEF OF BURVEY PARTY	DATE	
APPROVED AND SIGNED BY_	MICHIGAN REGISTERED LA	ND SURVEYOR DATE	(SEAL)