LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	LADEER
1. PUBLIC LAND SURVEY_	/3 T. 8 N. R. /0 E.	<u> </u>	1400
	<u>/3</u> , T. 8 №, R. /3 E.	K-6	
3. MISCELLANEOUS PROPERTY IN SECTION	, T		
4. LOT NO,	RECORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1921, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
		•	
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found R.R. Spike At Road Intersection			
This Counce	Jewall of Stephen	177/ = 2 S	bainsion
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
Railrond Spik	ie –		
5 50° F 5	6.35 24" Forked	ouk	
0, 30 E, 3	3.20 37" Maple		
5 25 W 3	3.20 37" Maple 36.60 Stop Sign 5.60 Stop Sign		
NICSE. 3	5,60 Stop Sign		
77. 6027	21.90		
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN	REGISTRATION NO.		(SEAL)
FOR STATE AND UNITE	D STATES AGENCIES:		
SIGNED BY		DATE	
	CHIEF OF SURVEY PARTY	b.mr	
APPROVED AND SIGNED	MICHIGAN REGISTERED LA	AND SURVEYOR DATE	(SEAL)