SURVEY & REMONUMENTATION

APR 28 1995

COMMISSION

1994 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

Filing

RECEIVED FOR RECORD

Requirement of Act 74, Mich. P.A. 1970	94 DEC 22 PM 2: 06
	1 10 50 NO 15 11 50 NO 18

z 110.282 For corners in MARATHON TWP. LAPEER (County) Corner Code # Halissal 2:2 Paugh REGISTER OF OFEUS LAFFER COLLED TO DIGAN Located In: T 09N R 09E 1. Public Land Survey M~9 2. Property Controlling Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. Lot No.
 Private Claims , Recorded Plat 8 C D E F G H I J K L M 2 5 2 1 6 I, JONATHAN M. FIELD , in a field survey on SEPTEMBER 23 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: 12 10 11 8 13 18 17 16 15 14 24 20 27 25 10 30 20 28 26 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 31 32 33 34 35 36 A. Description of original monument and accessories and/or subsequent restoration: 1852 GLO; WAMPLER, D.S.; SET POST; BEECH 7 N25 1/2W 13 1/2LKS, BEECH 10 S44W 22LKS.

1906 SICKLESTEEL, C.S.; STAKE; PINE 36 S20E 83LKS., PINE 34 S70W 28LKS.

1978 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.4, PG.546; NO OBJECT STATED; WEST 33.61' 10" OAK, NORTH 77.22' FND T-IRON, S45°W 29.88' 6" HICKORY, N20°E 55.95' 4" OAK

1980 BECK-GRAVLIN; BECK, P.S.#21559; SURVEY L.5, PG.913; 1/2" IRON; SAME WITS AS 1978 SURVEY 1985 GRAVLIN, P.S.#23510; SURVEY L.6, PG.945; FND 1/2" IRON; EAST 27.85' 6" POPLAR, S50°W

29.75' 10" HICKORY, N85°W 33.34' 10" OAK

1987 GRAVLIN, P.S.#23510; LCRC L.4, PG.233; FND 1/2" IRON; SAME WITS AS 1985 SURVEY ABOVE
1988 GRAVLIN, P.S.#23510; SURVEY L.7, PG.887; NO OBJECT STATED; SAME WITS AS 1978 SURVEY
1993 HENDERSON-BATES; ELRICH, P.S.#18986; SURVEY L.10, PG.387; FND 1/2" IRON; EAST 27.85' 6"
POPLAR, S50°W 29.75' 10" HICKORY, N15°E 78.52' UTILITY POLE, S20°E 64.93' 6" POPLAR

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ROWE ENG.; FIELD, P.S. #37276; FND 1/2" ROD (BENT & TWISTED) @ C/L GRAVEL ROAD N-S & ON
LINE W/ FE ROW TO W. RECOVERED 4 PREVIOUS WITNESSES INDICATING FND ROD IS IN SAME GLO NOTES OF T9N-R10E INDICATE THAT A-9 WAS SET POSITION AS 1978 BECK-GRAVLIN SURVEY 1.19 CH. N. OF M-9 T9N-R9E

2628.50' M-9 TO M-8 (MEAS. BY OTHERS)

ACCEPTED 1/2" ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION

				and and	accariac a	rtablishas	to perpetuate	a location th	e nosition	of the c	orner:
U. L M−9	REMOVED	BENT R	OD, SET	NEW 1/2	essolles es 2" ROD F	i/ STAN	DARD BRAS	S CAP	O P		
							FACE 14"				
							8" HICKO				
	EAST,	27.75	FND NA	IL W/FL	AG. IN V	. FACE	6" POPLA	R			
	N30°E,	55.87'	FND NA	IL W/FLA	G. IN W	. FACE	6" OAK				
	N20°E,										
	S20°E,	64.971	SET NA	IL W/ RE	MON TAG	ABOVE	FND NAIL	W/FLAG.	IN W.	FACE	B" POPLAR
	NORTH,										OF N

PEER GROUP APPROVED LAND CORNER PA 345 OF 1990

EXPESSIONATION M Fin Surveyor's Michigan License No. 37276

LIBER 7005 PASE 0182

M FIFLD LAND 37278

JONATHAN

RAY DAVIS P.S. CO. SURVEYOR DATE /2: 22-94