## BUHVEY & REMONUMENTATION

APR 2 9 1998

REMONUMENTATION

RECEIVED FOR RECORD

## COMMISSION

\_\_\_ , Recorded Plat \_

4. Lot No. 5. Private Claims \_\_\_

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

95 SEP -7 PH 3: 05

LAPEER		Located In: C	Corner Code ##	LIBER NOPAGE NO
	(County)	Burnside South	1-4	REGISTER OF REEDS LAPEES COUNTY, MICHIGAN
1.	Public Land Survey	T R T R T R		LAPEC COURT GIRDING
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number

Earl E.	Gravlin	July	19th	95
!,	, in a field	survey on		, 19 ,
in lines 1 and 2 current manual of Management or i above were in co	y that under requirements above were in conforma of survey instructions of t by a decree of a Court of L onformance with the rules established, re-establish	nce with regulations a he United States Depa aw and/or that the corn of the Michigan Board	nd rules therefor rtment of the Int er points mention of Land Surveyo	ore as required in the terior, Bureau of Land oned in lines 3, 4 and 5 ors or by a Decree of a

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

History: Parke 1834 Set Post Maple 9 S56W 3.5 Sugar 6 N9W 25, County Surveyor Bates 1865 Stake Sugar 22 N78E 135 Stake N87E 50 M-4 to M-3 40.15, Act 74 None, Recorded Surveys None, Unrecorded Surveys Brown 12/21/89 Job # 89-124 Set Pk nail from previous surveys, East 31.4 Spike 12" Cherry, S60E 35.20 to Mon, South 11.83 W 1/4 Cor Sec 7 T9N-R13E, Brown 7/7/93 Job # 93-86 same witnesses as Job # 89-124. Road Commission, W 31.67' Wood Cor. Post, E 30.62' 12" Stump, S50°E 43.85' 14" Stump. Drain Commission Nothing.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site Conditions: Found PK Nail, Level Farmland, Asphalt Road, M-4 to M-5 2656.04, M-4 to M-3 2633.33 M-4 to A-4 South 11.83 M-4 to Empty Mon Box South 3.77.

> PEER GROUP APPROVED LAND CORNER PA 345 OF 1990 AREER COUNTY

DAVIS P.S. CO. SURVEYOR 7-13-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

July 19th, 1995 FOUND PK NAIL, SET 1/2" IRON AND BRASS CAP IN MON BOX \$60°E 35.13' CONC. MON. \$25°E 34.33' NAIL & TAG W SIDE 12" ELM SOUTH 11.87 1/2" RE-ROD IN MON BOX N 25°E 73.53' NAIL & TAG W SIDE 8" ELM

Surveyor's Michigan License No.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

THE 3005 PAGE 0271

REVISED JAN., 1983