

**SURVEY &
REMONUMENTATION**

APR 29 1996

REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

95 SEP -7 PM 3: 01

For corners in

LAPEER

(County)

Located in:

Burnside North

10N 12E

Corner Code #

I-13

| | | | |
|------------------------------------|---|---|-------|
| 1. Public Land Survey | T | R | _____ |
| | T | R | _____ |
| | T | R | _____ |
| | T | R | _____ |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous Property in Sec. | S | T | R |
| | S | T | R |

LIBER NO. 5 PAGE NO. 267
Nelson Da Vaughn
REGISTER OF DEEDS
LAPEER COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

| | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

Earl E. Gravlin July 19th 95

I, _____, in a field survey on _____, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

History: Parke 1833 Set Post Elm 9 N51W 35.5 B. Ash 16 N30E 32, County Surveyor None, Act 74 None, Recorded Surveys Elrich L3 P622 Set 1/2" Iron, N10W 81.67 Buried Cable Post, N60W 189.91 PP, J-13 to I-13 2658.52, Unrecorded Surveys None. Road Commission, same as L3, P626, Drain Commission Nothing

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


Site Conditions: Found Nothing Reset 1/2" Iron from Recorded Survey, Level Farmland, Gravel Road East and West. Remains of fence and drain to North, GLO 2.5 CH, I-1 not found. I13 to J13 2658.52 I13 to H13 2657.18.

PEER GROUP
APPROVED LAND CORNER
PA 345 OF 1990
LAPEER COUNTY

Ray Davis
RAY DAVIS P.S. CO. SURVEYOR
DATE 7-13-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

July 19th, 1995
FOUND 1/2" IRON, SET BRASS CAP
15'± W C/L DRAIN TO NORTH
N74°W 189.89' NAIL & TAG S SIDE POWER POLE
N77°E 222.42' NAIL & TAG S SIDE POWER POLE
S78°E 236.71' NOTCH IN END OF 48" CMP
N10°W 81.63' FACE BURIED CABLE SIGN



Signed by *[Signature]*

Date 8-17-95

Surveyor's Michigan License No. 23570

LIBER 0005 PAGE 0267