


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

LEKLANAU COUNTY
T 28 N R 12 W

DESCRIPTION OF CORNER 1/4 corner common to sections 29-30
CORNER MONUMENT Found 2" Pipe at Fence Remains N-S-W. Added Cedar guard post.
DATE MONUMENT PLACED AND WITNESSED 7-1-69
WITNESSES TO CORNER.....



4" Maple S 21 E 6.4'
10" Ash N 70 W 27.8'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered during a retracement and boundary survey in this area. Old County Surveyor's records at the Register of Deeds Office, Fred Green County Surveyor 1914, call for a 2" pipe.

SURVEYOR'S SEAL

SIGNED

Carl F. Roever
REGISTERED LAND SURVEYOR 12028

DATE

8-8-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68