

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

LEKLANAU COUNTY


T 28 N R 12 W

DESCRIPTION OF CORNER Sec. corner common to sections 30-29-31-32

CORNER MONUMENT Found 1 1/2" Pipe. Added Std. Dept. Mon. with Cedar Guard Post

DATE MONUMENT PLACED AND WITNESSED 7-1-69

WITNESSES TO CORNER.....



<u>6" Ced.</u>	<u>S 45 W</u>	<u>38.3'</u>
<u>5" Ced.</u>	<u>S 82 E</u>	<u>66.2'</u>

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was recovered during a retracement and boundary survey in this area. Old County Surveyor notes, Fred Green 1914, show that he had this corner when he subdivided Sec. 30, but he did not describe the point.**

SURVEYOR'S SEAL

SIGNED

*Carl F. Roser*

DATE

8-8-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR **12028**

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68