STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			LEELAUNAU	COUNTY
			T <u>28 W</u>	R <u>13 W</u>
DESCRIPTION OF CORNER	1/4 corner common to Sections 25 & 36			
CORNER MONUMENT	Set 1"x20"	pipe in black top	road (M-72)	
DATE: MONUMENT PLACED AND	D WITNESSED	7-1-69		
WITNESSES TO CORNER	••	22" Maple	8 34 W	129.5'
N		12" B. Cherry Tw	a 8 3 W	98.51
25		Set PK Heil (Trv	.Point) N89°12'W	1.52'
	AND	Set Cedar Post	Due N	33'
CIRCLE CORNER REGISTE	RED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set during a retracement and boundary survey in this area. It was set by single proportion (to U.S.) between found section corners to E & W.

SURVEYOR'S SEAL

SIGNED

PECISTERED LAND SUPPLYOR 12028

8-8-69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing