


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

LEKLANAU COUNTY
T 28 N R 12 & 13 W

DESCRIPTION OF CORNER Sec. corner common to Sections 24-19-25-30
CORNER MONUMENT Found slight dip at corner fence post. (Fence N-S-W). Added
Std. Dept. Mon.
DATE MONUMENT PLACED AND WITNESSED 7-1-69
WITNESSES TO CORNER.....



14" Maple S 69 W 30.9'
12" Maple N 7 E 10.4'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered during a retracement and boundary survey in this area. Old County Surveyor's records called for iron at fence corner and Mr. Kasben* showed us this corner.

* Local Land Owner.

SURVEYOR'S SEAL

SIGNED

Carl F. Roer
REGISTERED LAND SURVEYOR 12028

DATE

8-8-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68