

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

LEKLANAU COUNTY


T 28 N R 13 W

DESCRIPTION OF CORNER 1/4 corner common to sections 25 & 26

CORNER MONUMENT Found 1 1/2" pipe buried in approximate intersection of road
E-W-N and in line with old fence to S.

DATE MONUMENT PLACED AND WITNESSED 4-30-69

WITNESSES TO CORNER..... No witnesses



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered during a retracement and boundary survey in this area. It is on record at the County Road Commission and fits the average lines of occupancy, roads and fences, for one-half mile to the E & W.

SURVEYOR'S SEAL

SIGNED

Carl F. Roer

DATE 8-8-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR **12028**

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68