SURVEY & REMONUMENTATION

MAR 04 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Filing Requirement	t of Act 74, Mich. P.A. 1970
<u>Leelanau</u> Located in: Corner C	Code# Barbara Kirt 12/31/98
TR	Leelanau Res of Deeds 9:55 am BJK Fee: 9.00 04800002 P0291 Page 1 of 1
T R	#594 Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
I, Nicholas M. O'Non , in a field survey on December 9 under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in conformance with regulations and rules therefore as required in the current of the United States Department of the Interior, Bureau of Land Management or by for that the corner points mentioned in lines 3, 4 and 5 above were in confiding an Board of Land Surveyors or by a Decree of a Court of Law; established recovered, found as expressed below:	ned in lines 1 and 2 above were nanual of survey instructions of a decree of a Court of Law and ormance with the rules of the
NOTE: Not more than 2 corners, all in the same town and range, may on this certificate.	
 A. Description of original monument and accessories and/or subsequences: A-9: West Section Corner Common to Sections 19 and 30. G.L.O. notes: Set post corner common to Sections 19, 30, 30 	13 1
Sugar 12", N51°W, 33 links Hemlock 8", S73°W, 29 links Hemlock 12", S75°E, 17 links Hemlock 36", N04°E, 30 links C.P. Tuller: Stone, 1888. P.J. O'Non: Stone with "x" and 19 on East side 1959.	
 B. Description of corner evidence found and/or method applied in re A-9: West Section Corner Common to Sections 19 and 30. Found 5/8" iron rod with cap #19846. Witnesses: 4" Tart Cherry, N89°W, 70.37' 16" Wild Cherry stump, S21°E, 37.75' 8" Ironwood stump, South, 33' +/- On fence line South 	APPROVED LAND CORNER P.A. 345 OF 1990 LEELANAU COUNTY DATE: 1210-98 COUNTY REP. 214.024
County Remonumentation Peer Review Group on Decemberstamped brass cap.	thful reestablishment of the position of the original corner by the Leelanau er 10, 1998 and replaced with a 3/4" galvanized iron pipe 3' long and a
16" Wild Cherry Stump, S21°E, 37.75' 8" Ironwood stump, South, 32.70' On fence line	erry, S80°E, 12.61')4°W, 41.44' South
Signed by Willela M. O'Mon	Date <u>12/29/98</u>
Surveyor's Michigan License No. 28420	