COMMISSION

STATE OF MICHIGAN COUNTY OF LEELANAU RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

1993 DEC 28 PM 4: 25

For corners in	i intig redune	inon or not 17, mon		Land	1	4/1	Ļ		
Leelanau (County)	Located In: Corner Code ##			Barbara Kirt REGISTER OF DEEDS					
Public Land Survey .	T <u>30N</u> R <u>11W</u> T R	F-1	FILE #328						
				LIBE	R 2 P	AGE 2	5		
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register	of Deed	s Stami	p & File	Numb	er	
4. Lot No , R	ecorded Plat		А	вс	DEF	GН	انا	K L M	
I, Steven P. Bye do hereby certify that under req in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance wit Court of Law; established, re expressed below: NOTE: Not more than 4 co on this certificate. A. Description of original re	in a field survey on December of P.A. 74, Michigan P.A. of conformance with regulations and account of Law and/or that the corner that the trules of the Michigan Board of re-established, monumented, re-morners, all in the same town and monument and accessories and ther, Section 4: G.I.O. White	er 20, 19 93 of 1970, the corner points mention of the lorer as required in ment of the Interior, Bureau of L r points mentioned in lines 3, 4 a f Land Surveyors or by a Decree nonumented, recovered, found of range, may be recorded from subsequent restoration:	the and 7 nd5 8 of a 9 1 as 10 11 12 13 on post"	-181 -192 -302	3		23-23-26-35-	12	
		20 - S 47 E, 30 lin							

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1: N 1/4 corner, Section 4: Found 1/2" iron of record - cap gone, iron bent Southward Re-established original position. 6.6' West of centerline of Jacobsen Rd., & 7.5' worth of centerline of Pobuda Rd.

Existing witnesses: SW corner barn - N 43 E, 106.98' SE corner garage - N 30 W, 153.93' Power pole - N 81 W, 25.12' (5'+ high)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1: N 1/4 corner SEction 4: 1/2" iron rod accepted by the Leelanau County Remonumentation Peer Group, December 9, 1993, and replaced with a 3/4" i.d. galvanized iron pipe 3' long with a brass cap.

New witnesses:

NW corner house foundation - S 46 E, 169.14'

Power pole - S 77 W, 120.36'

Signed by Steven P. Bye
-Surveyor's Michigan License No. 35991

te 10-22-93



DRM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983

25