1993

COMMISSION

Surveyor's Michigan License No. 30105

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF LEEL ANAU RECEIVED FOR RECORD

1993 DEC 28 PM 4: 23

For corners in		, , , , , , , , , , , , , , , , , , ,	\mathcal{J}_{2}	2 1 4/ 4
Leelanau	Located In:	Corner Code ##		arlara Kirt
(County)	•		RE	EGISTER OF DEEDS
1. Public Land Survey	T <u>31N</u> R <u>11W</u> T R			FILE # 306
•	T R		FOI	BER 2 PAGE 3
Property Controlling in Section	S T R S T R			
3. Miscellaneous	S T R		Register of Deeds	Stamp & File Number
Property in Sec.	S T R			
		× .		
•	lecorded Plat		A B C D	EFGHIJKLM
do hereby certify that under req in lines 1 and 2 above were in current manual of survey instrumanagement or by a decree of a above were in conformance with Court of Law; established, rexpressed below: NOTE: Not more than 4 coon this certificate.	а	P.A. of 1970, the corner points me and rules therefore as require partment of the Interior, Bureau riner points mentioned in lines 3 rd of Land Surveyors or by a Dec re-monumented, recovered, for a and range, may be recorded	ontioned d in the of Land 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
Beech 15 - N 44 W Hemlock 12 - N 69				
8. Description of corner ev	vidence found and/or metho	d applied in restoring or ree	stablishing comer:	
G-13: SE corner,		Found 1/2" iron rod on centerline of Pobuda Rd. and fenceline North.		
Existing witnesses 6" poplar - S 29 I 12" poplar - S 54 Power pole - N 75	E, 42.80' W, 83.97'	•		
	N.			
C. Description of monumer	nt for corner and accessorie	s established to perpetuate	locating the position of the	e corner:
G-13: SE corner,	G-13: SE corner, Section 33: 1/2" iron rod accepted by the Leelanau County Remonument Peer Group, December 9, 1993, and repalced with a 3/4" i galvanized iron pipe 3' long with a brass capulation.			
New witnesses:		•		in Shanning
Fence post - North	1 43.99'		i i	HOWARD
4" red pine - N 28			i i	* WALKER *

Date .