SURVEY & REMONUMENTATION

APR 28 1995

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

LIBER 001 PAGE 60

EH ET

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			FIFE ON
Lenawee	Located in:	Corner Code #	3.50
(County)			DEC 29 1994 3,51P, M
1. Public Land Survey	T <u>- 6 - S</u> R <u>- 1 - E</u> T R T R T R	<u>E-12</u>	LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
I, Glenn E. Richard do hereby certify that under in lines 1 and 2 above we current manual of survey in Management or by a decree above were in conformance	requirements of P.A. 74, Michigan P re in conformance with regulations a structions of the United States Depar of a Court of Law and/or that the core with the rules of the Michigan Board d, re-established, monumented, re	rvey on <u>December 13,</u> 19 A. of 1970, the corner points mer and rules therefore as required ritment of the Interior, Bureau of ner points mentioned in lines 3, 4 of Land Surveyors or by a Decr	94
•	l corners, all in the same town ar	nd range, may be recorded	12 31 32 33 34 35 36 13
G.L.O. October February 1880 June 1881, Jan February 1891 August 1919, V August 4, 1953 spike). March 25, 1975 4" spike and re March 1993, Th June 1993, Set	, 5, Found 4" boat spike and dug ecorded in L. 3, P. 147. ne monument was gone as roa	ost Dogwood 4 North 11, bunty Surveyor the corner corner but didn't describe the corner consisting of second corner from the corner from the forstone but found not ad was again under constrement by re-tracing surve	Hickory 12 S 72 W 22 r is labeled as a stone e the monument. stone. nter line. m witnesses taken on the road survey (small thing. Set 12" boat spike in location of found cruction. eys done North of the corner, as the remaining

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

December 13, 1994, Found 3/4" X 3' iron pipe capped G.E.R. 13040 in the pavement and set monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe capped G.E.R. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. dbl. hd. nail & disc in Elec. pole S 40° W 88.98

Fd. dbl. hd. nail & disc in Elec. pole S 85° E 64.70

SW. corner of Mobile home porch \$ 65° E 118.58 "X" cut on North end of 12" C.M.P. \$ 25° E 48.88

"X" cut on North end of 12" C.M.P. S 10° E 92.58

Face of 4" Well casing \$80° E88.64



	$\Theta(I) = A(I) I A(I)$	
Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Sant hickard Date December 22	. 1994_
Ratified by Peer Group in accordance with P.A. 345 Signed by Signed by	Date Dec 23, 1994	
Clonn E Dichard	•	

Surveyor's Michigan License No. 13040